

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8246U
MAKE HYUNDAI
MODEL IONIQ

DATE: 30.12.24
MVA JUMANI
DOA: 29.12.24

SOMPO

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY		7000	\$459.40
1	REAR BUMPER CENTRE MOULDING		7000	\$451.25
10	REAR BUMPER CLIPS		220	\$22.00
1	REAR BUMPER BEAM		11	\$394.80
1	REAR FOG LAMP ASSY		11	\$201.50
1	ANTENNA SMARTKEY		11	\$40.50
	SUB TOTAL			\$1,569.45
	LESS 25%			\$392.35
	DISCOUNTED TOTAL			\$1,177.09
	REVERSE SENSOR		mol/fraction	\$180.00
	REAR NUMBER PLATE		scr	\$55.00
	LESS 10%			
	SUB TOTAL NET			\$235.00
	Labour Charge			
	PANEL BEATING		380	\$400.00
	SPRAY PAINT		280	\$300.00
	REMOVE / REFIX REVERSE SENSOR		30	\$50.00
	TOTAL LABOUR			\$750.00
	ESTIMATE TOTAL			\$2,162.09
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 932-65
252
699-48
220
890
1609-48
222
1281

**COMFORTDELGRO
ENGINEERING**

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305614204

Date 04.01.25

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr MARCUS

Vehicle Reg No. SHC8246U

Date of Accident : 29.12.24

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **SOMPO** --- **FBQ4652D**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$1,300.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : MARCUS

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$27.25 / 2.18	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: