

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT
SINGAPORE 415875
TEL: 96311088

TO	: NTUC	DATE	: 6/1/2025
VEHICLE NO	: SNM4167S (2018)	<i>Xiao Chen.</i>	
VEHICLE MODEL	: MERCEDES BENZ C180 COUPE		
CHASSIS NO	: WDD2053402F738214		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR <i>Defect</i>	1	\$ 3,185.00	\$ 3,185.00
2	FRONT DOOR LOCK <i>Not in</i>	1	\$ 581.00	\$ 581.00
3	FRONT DOOR WEATHERSTRIPE <i>Not in</i>	1	\$ 289.00	\$ 289.00
4	FRONT DOOR INNER TRIM BOARD <i>Not in</i>	1	\$ 1,055.00	\$ 1,055.00
5	FRONT DOOR GLASS REGULATOR GEAR <i>Not in</i>	1	\$ 310.00	\$ 310.00
6	FRONT DOOR GLASS REGULATOR MOTOR <i>Not in</i>	1	\$ 565.00	\$ 565.00

TOTAL PRICE: \$ 5,985.00
LESS 10% \$ 598.50
SUB TOTAL PRICE: \$ 5,386.50

3784
3405.60

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR INNER TRIM BOARD CLIPS <i>Not in</i>	1 SET	\$ 50.00	\$ 50.00
TOTAL :				\$ 50.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	<i>200</i>	
3	WIRING CHECK	\$ 50.00	<i>x</i>	
6	TO TRANSFER FRONT DOOR FITTINGS	\$ 150.00	<i>60</i>	
7	TO APPLY TUFF COAT	\$ 150.00	<i>x</i>	
TOTAL:		\$ 1,150.00		

460

ESTIMATE REPORT

TOTAL PARTS COST: \$ 5,436.50
TOTAL LABOUR COST: \$ 1,150.00
TOTAL REPAIR COST: \$ 6,586.50

total: 3865.60
h/s: 3K
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: