



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 2750C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP LH	CUT	2,970.40	2,970.40
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	169.80	-
1	FRONT GRILLE	NOT NECESSARY	1,400.50	-
1	FRONT GRILLE LOGO	NOT NECESSARY	91.80	-
1	FRONT BUMPER	DEFORMED	1,550.60	1,185.00
1	FRONT BUMPER MIDDLE BRACKET LOWER (INNER)	NOT NECESSARY	310.20	-
1	FRONT BUMPER CHROME LOWER LH	NOT NECESSARY	110.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	456.50	-
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	292.00	-
1	FRONT BUMPER FOG LAMP COVER LH	NOT NECESSARY	101.80	-
2	FRONT BUMPER SIDE RETAINER R/L	NOT NECESSARY	292.20	-
2	FRONT SENSOR	NOT NECESSARY	610.00	-
1	FRONT FENDER LH	DENTED	885.00	885.00
1	FRONT FENDER INNER SHIELD LH	DEFORMED	256.80	256.80
1	FRONT FENDER SIDE BRACKET PANEL LH	NOT NECESSARY	530.50	-
	LESS 20% DISCOUNT		-2,005.62	-1,059.44
			8,022.48	4,237.76
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	100.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SETS FRONT FENDER INNER SHIELD CLIP R/L (SN)	NECESSARY	60.00	30.00
			210.00	60.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN AFFECTED AREA.		1,200.00	600.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA.		1,000.00	700.00
	TO CHECK WIRING AND HEAD LAMP FOCUS.		120.00	30.00
	TO DIAGNOSIS & RESET AFTER WORK.	NOT NECESSARY	300.00	-
			2,620.00	1,330.00
	GRAND TOTAL		10,852.48	5,627.76

Report Ref No. CS/INC24120463/Avh3m4(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,500.00
---	--	--	-----------------

Report Ref No. CS/INC24120463/Avh3m4(N)

TOTAL FOR SPARE PARTS: \$ 8,232.48 \$ 4,297.76

TOTAL FOR LABOUR : \$ 2,620.00 \$ 1,330.00

TOTAL REPAIR COST: \$10,852.48 \$ 5,627.76

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.