

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 30.12.2024

TO : MSIG MOTOR CLAIMS DEPTS
VEHICLE NO : SMJ3483M
MODEL : HONDA SHUTTLE
DATE OF ACCIDENT : 23.12.2024
TIME OF ACCIDENT : 11:10 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Defect</i>	1	\$ 1,600.00	\$ 1,600.00
2	REAR BUMPER EXHAUST COVER GARNISH	1	\$ 57.00	\$ 57.00
3	REAR BUMPER REFLECTOR <i>crack'd RH</i>	2	\$ 49.00	\$ 98.00
4	REAR BUMPER REFLECTOR GARNISH <i>new</i>	2	\$ 68.00	\$ 136.00
5	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 19.00	\$ 19.00
6	REAR BUMPER SIDE INNER BRACKET <i>RH crack'd</i>	2	\$ 39.00	\$ 78.00
7	REAR BUMPER SPONGE <i>crack'd RH</i>	2	\$ 47.00	\$ 94.00
8	REAR BUMPER SIDE RETAINER <i>RH crack'd</i>	2	\$ 32.00	\$ 64.00
9	TAIL GATE <i>Repair</i>	1	\$ 1,900.00	\$ 1,900.00
10	TAIL GATE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
11	TAIL GATE EMBLEM 'SHUTTLE' <i>yellow</i>	1	\$ 70.00	\$ 70.00
12	TAIL GATE EMBLEM 'HYBRID'	1	\$ 98.00	\$ 98.00
13	TAIL GATE STOPPER <i>new</i>	2	\$ 25.00	\$ 50.00
14	TAIL GATE INNER LOCK <i>new</i>	1	\$ 190.00	\$ 190.00
15	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 24.00	\$ 24.00
16	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 190.00	\$ 190.00
17	TAIL GATE DETECTOR <i>new</i>	1	\$ 296.00	\$ 296.00
18	TAIL GATE INNER TRIM <i>new</i>	1	\$ 320.00	\$ 320.00
19	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 160.00	\$ 160.00

985
+
49
+
+
39
47
32
+
+
✓
✓
+
+
+
+
+
+
+

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMJ3483M**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 23.12.2024
 TIME OF ACCIDENT : 11:10 HOURS

20	TAIL LAMP RH <i>new</i>	2	\$ 520.00	\$ 1,040.00	+
21	TAIL LAMP LOWER PANEL (OUTER) <i>RH Bent</i>	2	\$ 272.00	\$ 544.00	+ 272
22	REAR FENDER COWLING <i>new</i>	2	\$ 147.00	\$ 294.00	+
23	REAR FENDER INNER TRIM RH <i>new</i>	1	\$ 550.00	\$ 550.00	+
24	REAR FENDER AIR VENT RH <i>new</i>	1	\$ 58.00	\$ 58.00	+
25	REAR END PANEL <i>Repair</i>	1	\$ 920.00	\$ 920.00	+
26	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 155.00	\$ 155.00	+

1592

1273.60

TOTAL PRICE \$ 9,050.00
 LESS 20% \$ 1,810.00
SUB TOTAL PRICE \$ 7,240.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
2	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
3	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	TAIL GATE WINDSCREEN SEALANT <i>2</i>	1	\$ 80.00	\$ 80.00	+
5	TAIL GATE WINDSCREEN INNER SEAL <i>1</i>	1	\$ 60.00	\$ 60.00	+
6	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
7	TAIL LAMP LOWER PANEL (OUTER) SELANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
8	REAR FENDER INNER COWLING (SET) <i>2</i>	1	\$ 80.00	\$ 80.00	+
9	REAR FENDER INNER TRIM CLIPS (SET) <i>1</i>	1	\$ 80.00	\$ 80.00	+
10	REAR END PANEL INSULATION SEAL <i>1</i>	1	\$ 150.00	\$ 150.00	1
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
12	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	+

30

TOTAL \$ 1,120.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMJ3483M**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 23.12.2024
 TIME OF ACCIDENT : 11:10 HOURS

3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	x
5	REMOVE AND REFIX REAR VIDEO RECORDER	\$ 80.00	x
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	x
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	x
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

1050

TOTAL \$ 3,790.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,360.00
 TOTAL LABOUR COST : \$ 3,790.00
 TOTAL REPAIR COST : \$ 12,150.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian Lj
 2/2 31/12/24.
 09 days.

total: 2353.60

h/s: 1850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: