

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : MS FIRST Capital Insurance Ltd
16 Raffles Quay #42-01
Hong Leong Building
Singapore 048581

TEL: FAX:
ATTN: Motor Claim Department

ESTIMATE

No : 24122802
Date : 28/12/2024
Policy No : DMCVSNA020061082405
Veh Reg No : GBE2712R
Make / Model : NISSAN CABSTAR
Your Ref No : 24/FC/TP-249(12)
Claim Type : Third Party
Accident Date : 26/12/2024
TP Veh Reg No : SHC1760Y

*not found
merang
3/1/25
2 days
2/5/25
the ph. Atk. 1/2/25*

p/p 81431.90

Discription	Quantity	List Price	Amount
NET PRICE:			
1 TAIL GATE	1 PC	\$1,685.50	X
2 TAIL LAMP	2 PCS <i>n/s one</i>	\$315.50	0/500 \$631.00 <i>1/2</i>
3 TAIL LAMP BRACKET	2 PCS	\$125.00	1/1 \$250.00 X
4 REAR CORNER RUBBER BUSH <i>at 2/4</i>	1 PC	\$25.50	✓
5 TAIL GATE "NISSAN" STICKER	1 PC	\$125.50	X
			\$2,717.50
			Less 10%
			\$271.75
			\$2,445.75

- SPECIAL NET:**
- 1 REAR NUMBER PLATE
 - 2 *1 set* REVERSE SENSOR
 - 3 70KM/H STICKER
 - 4 6 PAX STICKER
 - 5 REAR STEP PANEL

*500 \$35.00 ✓
Torn \$250.00 200
1/1 \$20.00 X
1/1 \$20.00 X
Burt \$220.00 ✓*

TOTAL **\$545.00**

- Labour**
- 1 WIRE CHECKING
 - 2 REMOVE & REFIX TAIL GATE ALUMINIUM PLATE
 - 3 REMOVE & REFIX REAR SENSOR
 - 4 LABOUR CHARGE
 - 5 SPRAY PAINTING

*\$20.00 ✓
1/1 \$150.00 X
1/1 \$80.00 X
400 \$850.00
250 \$750.00*

TOTAL **\$1,850.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Amount Before GST **\$4,840.75**
Add GST @9% **\$435.67**
Total Amount Payable **\$5,276.42**

For SME MOTOR PTE LTD

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE