

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Wan, Haohui

Date: 05 Aug 2024

Preliminary Advice

Vehicle No	: SCF1777T	Accident Date	: 29/06/2024
Make	: AUDI Q5	Policy No.	: 2100510083
Assignment Date	: 02/07/2024	Excess	: S\$1,500.00
Date of Inspection	: 03/07/2024	Est. Duration of Repair	: 3
Inspection At	: 24 BENOI SECTOR PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,824.44	(INCLUSIVE OF SUPPLEMENTARY)
Revised Amount	:S\$	24,311.04	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	24,311.04	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	49,005.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,995.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.