

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24120469/AVP3E2
Date: 09/01/2025REFERENCE**Insured/Claimant:** FU WAN PEI, CHERYLIN (HU WANPEI, CHERYLIN)
Date of Loss: 29/12/2024**Policy No:** 2100485002
Nature of Claim: OD **Claim No:** 1767209043SGDESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** SLG4090J
Make & Model: AUDI TT, 1.8 COUPE TFSI S-TRONIC (A)
Reg. Date: 29/09/2016 (Man. Year: 2015)
Colour: Grey
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**
Engine No: CHH119261
Chassis No: TRUZZZFV9G1010931
Odometer: 70057 kmCONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size:** 245/40 R18 **Rear Tyre Size:** 245/40 R18
Front Left Side: Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm
Front Right Side: Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
Nett Amount (\$\$)	-1,600.00	-1,600.00	0.00	0.00

INSPECTION**Date of Assignment:** 31/12/2024**Date Inspected:** 06/01/2025 **Inspected At:**Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699**Estimated Period of Repair:** 0.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$58,000.00
OMV :	\$50,784.00
PARF Rebate (1) :	\$34,876.00
Quota Premium Paid :	\$55,501.00
COE Rebate (2) :	\$9,589.00
Total Rebate (1) + (2) = :	\$44,465.00

The total amount incurred will be Market Value \$58,000.00 minus Total Rebate \$44,465.00 = \$13,535.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >