

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 13 Jan 2025)

Parts: 143 **HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SNG8898X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

2nd Supplementary

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH headlamp top chrome	0.00	0.00	cash *120.00 F
2	1		*RH headlamp top chrome garnish	0.00	0.00	cash 120.00
3	1		*RH headlamp lower bracket	0.00	0.00	cash *60.00 F
4	1		*Air con outer temperature sensor bracket	0.00	0.00	dis *15.00 F
5	1		*Bonnet stand clip	0.00	0.00	de *12.00 F
6	1		*RH headlamp top chrome	0.00	0.00	cash *120.00 F

F=Franchise part.

Sub Total (\$\$)	327.00
+ Margin on L,N Items 10.00% (\$\$)	32.70
Total Parts (\$\$)	359.70

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Reamy Taufik 14/1/25 2:11:50pm

447
+10%
491.70