

Charn's Customcraft (Co.Reg.No:25151300M)

Block 1010 Bukit Merah Lane 3, #01-105

Singapore 159724

Tel: 62717054 Fax: 62736676 Email: charns@singnet.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24P00259800	Date of Loss:	19/12/2024
Vehicle Reg. No.:	SNG8898X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG CHOW LENG STANLEY	Contact No:	+6597988898
Make/Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Vehicle Reg. Date:	09/07/2019
Vehicle Colour:	RED	Chassis No:	MRHFC5650KT000646
Engine No:	R16B25510688		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	CHARN'S CUSTOMCRAFT (HQ)		

COST OF CLAIMS	Amount
Parts	6,950.90
Miscellaneous Items	70.00
Labour	1,890.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,910.90
+ GST 9.00% (S\$)	801.98
Nett Amount (S\$)	9,712.88

This claim is handled by: SHARON LEE CHIA LING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 25 Dec 2024)

Parts: 143

HONDA CIVIC 1.6 VTJ CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Charn's Customcraft/SNG8898X/25/12/2024 22:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front windscreen / BR	0.00	0.00	*1,350.00 F
2	1		*Front windscreen chrome moulding / PC	0.00	0.00	*130.00 F
3	1		*Bonnet / OD	0.00	0.00	-
4	1		*Bonnet hinge / BT	0.00	0.00	*100.00 F
5	1		*Front bumper / PR	0.00	0.00	*340.00 F
6	1		*Front bumper retainer / DR	0.00	0.00	*36.00 F
7	1		*Front bumper retainer top seal / CM	0.00	0.00	*38.00 F
8	1		*Headlamp RHS / DR	0.00	0.00	*940.00 F
9	1		*Grille / BR	0.00	0.00	*120.00 F
10	1		*Grille LHS / BR	0.00	0.00	*100.00 F
11	1		*Grille RHS / BR	0.00	0.00	*100.00 F
12	1		*Support panel garnish	0.00	0.00	*50.00 F
13	1		*Front bumper fog light chrome (RH) / CR	0.00	0.00	*130.00 F
14	1		*Front fender RHS / OD	0.00	0.00	*210.00 F
15	1		*Front fender LHS / OD	0.00	0.00	*210.00 F
16	1		*Front fender inner shield RHS / TN	0.00	0.00	*60.00 F
17	1		*Air con condenser X	0.00	0.00	*365.00 F
18	1		*Air con fan motor Y	0.00	0.00	*370.00 F
19	1		*Air con fan blade Y	0.00	0.00	*75.00 F
20	1		*Air con fan cowling X	0.00	0.00	*125.00 F
21	1		*Radaiitor X	0.00	0.00	*550.00 F
22	2		*Radaiitor side garnish (RH) / BR	0.00	0.00	*120.00 F
23	1		*Support panel / OD	0.00	0.00	*550.00 F
24	1		*Logo / CM	0.00	0.00	*30.00 F
25	1		*Air con suction pipe X	0.00	0.00	*130.00 F
26	1		*Air con liquid pipe (receiver pipe) X	0.00	0.00	*90.00 F

F=Franchise part.

Sub Total (\$\$) 6,319.00
+ Margin on L,N Items 10.00% (\$\$) 631.90

Total Parts (\$\$) 6,950.90

Charn's Customcraft/SNG8898X/25/12/2024 22:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 Front no.plate - S/nett	35.00
2	1 Radiator coolant - S/nett	35.00
Sub Total (\$\$)		70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove and replace a/c condenser including refill gas	New	100.00
2	Check wiring function	New	40.00
3	Remove necessary parts; jacking panel beating, repair and straighten front inner panel inclusive replacing the above.	New	700 750.00
4	Putty and respray front inner panel, bonnet, support panel, front fenders LHS/RHS and front bumper	New	800 1,000.00
Gross Labour Cost (\$\$)			1,890.00

Charn's Customcraft/SNG8898X/25/12/2024 22:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK) +6010-9429541

Steve.chen@lkk auto.com

2/1/25, 10 am

OD- New AL

Excess - \$600

L/S

4 AL 4
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: