

Supp 8898

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2025)
Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Charn's Customcraft/SNG8898X/10/01/2025 10:23
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper reinforcement	0.00	0.00	67-370.00 F
Sub Total (\$)						370.00
+ Margin on L,N Items 10.00% (\$)						37.00
Total Parts (\$)						407.00

Charn's Customcraft/SNG8898X/10/01/2025 10:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Rowley Tanjil 10/1/26 @ 10:40am

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Windscreen sealant - (S/NETT)	35.00
Sub Total (\$\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove and replace front windscreen.	New	150.00
Gross Labour Cost (\$\$)			150.00

Charn's Customcraft/SNG8898X/10/01/2025 10:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >