

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0136/2024
DATE : 01-JUL-2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : NEO LAN SEE
ADDRESS : 18 CANBERRA DRIVE #13-40
EIGHT COURTYARDS
S(768098)
TELEPHONE NO : 98288287

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10326267OR04 AUTO & GENERAL
VEHICLE NO : SLZ9598D
MODEL CODE : GT7BKVL
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YC50692
CHASSIS NO : JF1GT7KL5JG029294
MILEAGE : 1 KM
DATE IN : 01/07/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 01/07/2024

Print Date : 15/08/2024
Print Time : 11:07:08

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ9598D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST MS FIRST CAP - SH8443K		
2	ZZ/001	DOA:26/JUN/2024 TIME:1655 HRS LOC:SLIP ROAD FROM YISHUN AVE 2 TO AVE 7		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM & TAILGATE	5000.00	1360.00
4	ZZ/003	RESPRAY REAR BUMPER & TAILGATE	4500.00	1200.00
5	ZZ/004	TO SUPPLY PARKING SENSOR (2 PC SENSOR TYPE) (S/N)	360.00	360.00
6	ZZ/005	TO RMV, INSP & TRF TAILGATE LOCK & MOTOR, WIPER ASSY, TAIL-LIGHT, RR SPOILER & ATCH PART (S/N)	280.00	280.00
7	ZZ/006	TO RMV & REFIT BT.LID SIDE TRIMS, S/TIRE FLOOR, S/TIRE & TOOL FOR S/TYRE FLOOR REPAIRS (S/N)	200.00	.00
8	ZZ/007	TO RMV & RENEW REAR WINDSCREEN (S/N)	300.00	300.00
9	ZZ/008	TO SUPPLY WINDSCREEN SEALANT (S/N)	120.00	120.00
10	ZZ/009	TO SUPPLY & INSTALL REAR SOLAR FILM (S/N)	180.00	180.00
11	ZZ/011	TO SUPPLY AND APPLY ANTI-RUST COATING (S/N)	350.00	.00
12	ZZ/012	CARRY OUT DIAGNOSTIC CHECKS & RESET SYSTEMS (S/N)	320.00	320.00
13	ZZ/013	SUNDRIES	100.00	30.00
14	ZZ/014	RESPRAY REAR BUMPER BEAM (0.5 SUPP)	300.00	300.00 ✓ SUPP
15	ZZ/10	TO SUPPLY AND APPLY BODY SEALANT (S/N)	200.00	.00
TOTAL LABOUR CHARGES			12210.00	4450.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ9598D

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FLOOR PAN R R CP 5D	52129FL0209P			467.00	X
2	SKIRT COMPL R 5D	52401FL0209P			312.00	X
3	BUMPER FACE R XV	57704FL250			448.00	OK
4	BRKT SD R XV RH	57707FL400			14.00	X
5	BRKT SD R XV LH	57707FL410			14.00	X
6	BRKT LWR R *2	57707FL510			28.00	X
7	BEAM COMPL R EU	57711FL0419P			220.00	OK
8	COVER HOOK R XV	57731FL570NN			7.00	OK
9	PANEL COMPL R GAT	ORDER TCS 60809FL0009P			987.00	OK
10	GLASS ASSY R G	63019FL030			1148.00	OK
11	WSTR DR R G	63516FL000			117.00	X
12	DAM RUBBER	65245FL000			20.00	OK
13	CLIP BMPR *11PCS	909140007			33.00	OK
14	CLIP *4PCS	909140062			16.00	OK
15	CLIP *2PCS (REAR MUD GUARD CLIP)	909140065			4.00	OK
16	LETTER MK R	93079FL100			98.00	OK
17	LETTER MK R XV	93079FL140			39.00	OK
18	EYE SIGHT EMBLEM (TCS)	LPH010ES-EMB		SUPP	47.00	NEC ✓ OK
SUB TOTAL			0.00	0.00	3067.00	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	3067.00	0.00
OVERALL TOTAL			3067.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLZ9598D

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	3067.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	4450.00
TOTAL SPARE PARTS CHARGES	3067.00

TOTAL CHARGES	7517.00
ADD 9 % GST	676.53

GRAND TOTAL	8193.53
