

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0136/2024
DATE : 01-JUL-2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : NEO LAN SEE
ADDRESS : 18 CANBERRA DRIVE #13-40
EIGHT COURTYARDS
S(768098)
TELEPHONE NO : 98288287

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P103262670R04 AUTO & GENERAL
VEHICLE NO : SLZ9598D
MODEL CODE : GT7BKVL
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YC50692
CHASSIS NO : JF1GT7KL5JG029294
MILEAGE : 1 KM
DATE IN : 01/07/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 01/07/2024

Print Date : 01/07/2024
Print Time : 17:54:25

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ9598D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST MS FIRST CAP - SH8443K		
2	ZZ/001	DOA:26/JUN/2024 TIME:1655 HRS LOC:SLIP ROAD FROM YISHUN AVE 2 TO AVE 7		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL,S/TIRE FLOOR & TAILGATE	5000.00	1360 ✓
4	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL,S/TIRE FLOOR & TAILGATE	4500.00	1200 ✓
5	ZZ/004	TO SUPPLY PARKING SENSOR (2 PC SENSOR TYPE) (S/N)	360.00	hw ✓
6	ZZ/005	TO RMV, INSP & TRF TAILGATE LOCK & MOTOR, WIPER ASSY, TAIL-LIGHT, RR SPOILER & ATCH PART (S/N)	280.00	✓
7	ZZ/006	TO RMV & REFIT BT.LID SIDE TRIMS, S/TIRE FLOOR, S/TIRE & TOOL FOR S/TYRE FLOOR REPAIRS (S/N)	200.00	7XNN
8	ZZ/007	TO RMV & RENEW REAR WINDSCREEN (S/N)	300.00	✓
9	ZZ/008	TO SUPPLY WINDSCREEN SEALANT (S/N)	120.00	✓
10	ZZ/009	TO SUPPLY & INSTALL REAR SOLAR FILM (S/N)	180.00	✓
11	ZZ/011	TO SUPPLY AND APPLY ANTI-RUST COATING (S/N)	350.00	7XNN
12	ZZ/012	CARRY OUT DIAGNOSTIC CHECKS & RESET SYSTEMS (S/N)	320.00	✓
13	ZZ/013	SUNDRIES	100.00	30.
14	ZZ/10	TO SUPPLY AND APPLY BODY SEALANT (S/N)	200.00	7XNN
TOTAL LABOUR CHARGES			11910.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ9598D

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
1	FLOOR PAN R R CP 5D	52129FL0209P			467.00 ? XNN
2	SKIRT COMPL R 5D	52401FL0209P			312.00 ? XNN
3	BUMPER FACE R XV	57704FL250			448.00 de ✓
4	BRKT SD R XV RH	57707FL400			14.00 ? XNN
5	BRKT SD R XV LH	57707FL410			14.00 ? XNN
6	BRKT LWR R *2	57707FL510			28.00 ? XNN
7	BEAM COMPL R EU	57711FL0419P			220.00 ? ✓ BT
8	COVER HOOK R XV	57731FL570NN			7.00 mis ✓
9	PANEL COMPL R GAT	ORDER TCS 60809FL0009P			987.00 bt ✓
10	GLASS ASSY R G	63019FL030			1148.00 ne ✓
11	WSTR DR R G	63516FL000			117.00 X NN
12	DAM RUBBER	65245FL000			20.00 ne ✓
13	CLIP BMPR *11PCS	909140007			33.00 ne ✓
14	CLIP *4PCS	909140062			16.00 ne ✓
15	CLIP *2PCS (REAR MUD GUARD CLIP)	909140065			4.00 ne ✓
16	LETTER MK R	93079FL100			98.00 ne ✓
17	LETTER MK R XV	93079FL140			39.00 ne ✓
SUB TOTAL			0.00	0.00	3972.00 0.00
LESS DISCOUNT ()			0.00	0.00	0.00 0.00
GRAND TOTAL			0.00	0.00	3972.00 0.00
OVERALL TOTAL			3972.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

I ZZ/014 RESPRAY REAR BUMPER BEAM (0.5 SUPP) 300.00 300.00 ✓ SUPP

18 EYE SIGHT EMBLEM (TCS) LPH010ES-EMB SUPP 47.00 NEC ✓ OK

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLZ9598D

TOTAL LABOUR CHARGES	11910.00
TOTAL SPARE PARTS CHARGES	3972.00
GRAND TOTAL	15882.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Tanjin 12495445
WP 4/7/24 & 11/24
P/P Resung before paint
At Resung cheek (ten)
Tanjin c/ltan to an
25 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.