

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0136/2024
DATE : 01-JUL-2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : NEO LAN SEE
ADDRESS : 18 CANBERRA DRIVE #13-40
EIGHT COURTYARDS
S(768098)
TELEPHONE NO : 98288287

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P103262670R04 AUTO & GENERAL
VEHICLE NO : SLZ9598D
MODEL CODE : GT7BKVL
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YC50692
CHASSIS NO : JF1GT7KL5JG029294
MILEAGE : 1 KM
DATE IN : 01/07/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 01/07/2024

Print Date : 01/07/2024
Print Time : 17:54:25

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ9598D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST MS FIRST CAP - SH8443K		
2	ZZ/001	DOA:26/JUN/2024 TIME:1655 HRS LOC:SLIP ROAD FROM YISHUN AVE 2 TO AVE 7		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL,S/TIRE FLOOR & TAILGATE	5000.00	
4	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL,S/TIRE FLOOR & TAILGATE	4500.00	
5	ZZ/004	TO SUPPLY PARKING SENSOR (2 PC SENSOR TYPE) (S/N)	360.00	
6	ZZ/005	TO RMV, INSP & TRF TAILGATE LOCK & MOTOR, WIPER ASSY, TAIL-LIGHT, RR SPOILER & ATCH PART (S/N)	280.00	
7	ZZ/006	TO RMV & REFIT BT.LID SIDE TRIMS, S/TIRE FLOOR, S/TIRE & TOOL FOR S/TYRE FLOOR REPAIRS (S/N)	200.00	
8	ZZ/007	TO RMV & RENEW REAR WINDSCREEN (S/N)	300.00	
9	ZZ/008	TO SUPPLY WINDSCREEN SEALANT (S/N)	120.00	
10	ZZ/009	TO SUPPLY & INSTALL REAR SOLAR FILM (S/N)	180.00	
11	ZZ/011	TO SUPPLY AND APPLY ANTI-RUST COATING (S/N)	350.00	
12	ZZ/012	CARRY OUT DIAGNOSTIC CHECKS & RESET SYSTEMS (S/N)	320.00	
13	ZZ/013	SUNDRIES	100.00	
14	ZZ/10	TO SUPPLY AND APPLY BODY SEALANT (S/N)	200.00	
TOTAL LABOUR CHARGES			11910.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ9598D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	FLOOR PAN R R CP 5D	52129FL0209P			467.00		
2	SKIRT COMPL R 5D	52401FL0209P			312.00		
3	BUMPER FACE R XV	57704FL250			448.00		
4	BRKT SD R XV RH	57707FL400			14.00		
5	BRKT SD R XV LH	57707FL410			14.00		
6	BRKT LWR R *2	57707FL510			28.00		
7	BEAM COMPL R EU	57711FL0419P			220.00		
8	COVER HOOK R XV	57731FL570NN			7.00		
9	PANEL COMPL R GAT	60809FL0009P			987.00		
10	GLASS ASSY R G	63019FL030			1148.00		
11	WSTR DR R G	63516FL000			117.00		
12	DAM RUBBER	65245FL000			20.00		
13	CLIP BMPR *11PCS	909140007			33.00		
14	CLIP *4PCS	909140062			16.00		
15	CLIP *2PCS (REAR MUD GUARD CLIP)	909140065			4.00		
16	LETTER MK R	93079FL100			98.00		
17	LETTER MK R XV	93079FL140			39.00		
SUB TOTAL			0.00	0.00	3972.00	0.00	
LESS DISCOUNT ()			0.00	0.00	0.00	0.00	
GRAND TOTAL			0.00	0.00	3972.00	0.00	
OVERALL TOTAL			3972.00				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLZ9598D

TOTAL LABOUR CHARGES	11910.00
TOTAL SPARE PARTS CHARGES	3972.00

GRAND TOTAL	15882.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.