

Front: _____ Date: _____
 Estimator: _____
 OD / ~~TP~~ RES / OD RES / EVA / INV / MV
 To in ~~Vehicle~~ Vehicle No: _____
 at VVO ~~in~~ _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Express: _____
 (Client Record)
 Make of Vehicle: _____

Remark: The veh had commenced its repair at the time of inspection.

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

046c

7	Others	1
---	--------	---

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 92398048

TAX INVOICE

Repair Code : CLM16349

Date in : 01/07/2024

Vehicle Num. : SMG6101L

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72000329/LEB7100551

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Defect</i>	1	1350.60	1,350.60 <i>885</i>
REAR BUMPER RH REFLECTOR <i>new</i>	1	45.00	45.00 <i>+</i>
REAR BUMPER RH REFLECTOR GARNISH <i>new</i>	1	45.00	45.00 <i>+</i>
REAR BUMPER RH SIDE RETAINER <i>new</i>	1	26.50	26.50 <i>+</i>
REAR BUMPER RH SPONGE <i>new</i>	1	89.50	89.50 <i>+</i>
REAR BUMPER TOW HOOK COVER <i>new</i>	1	16.50	16.50 <i>+</i>
REAR BUMPER UNDER COVER RH <i>new</i>	1	95.20	95.20 <i>+</i>
REAR END PANEL <i>Repair</i>	1	560.80	560.80 <i>+</i>
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	85.00	85.00 <i>+</i>
REAR END PANEL INNER TOP GARNISH <i>Defect</i>	1	155.50	155.50 <i>✓</i>
REAR RH FENDER INNER TRIM GARNISH <i>new</i>	1	489.60	489.60 <i>+</i>
REAR RH TAILLAMP <i>new</i>	1	520.50	520.50 <i>✓</i>
REAR TAILGATE <i>Defect</i>	1	1193.00	1,193.00 <i>✓</i>
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	38.00	38.00 <i>+</i>
REAR TAILGATE 'SHUTTLE' EMBLEM <i>new</i>	1	55.00	55.00 <i>✓</i>
REAR TAILGATE DAMPER L/R <i>new</i>	2	165.00	330.00 <i>+</i>
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	25.00	25.00 <i>+</i>
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	18.50	37.00 <i>+</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 92398048

TAX INVOICE

Repair Code : CLM16349

Date in : 01/07/2024

Vehicle Num. : SMG6101L

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72000329/LEB7100551

REAR TAILGATE INNER TRIM GARNISH <i>new</i>	1	320.00	320.00	+
REAR TAILGATE LOCK STRIKER <i>new</i>	1	27.50	27.50	+
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	157.10	157.10	+
REAR TAILGATE RH REFLECTOR <i>new</i>	1	25.00	25.00	+
REAR TAILGATE RH REFLECTOR INNER RUBBER GASKET <i>new</i>	1	25.00	25.00	+
REAR TAILGATE WEATHER STRIP <i>new</i>	1	168.50	168.50	+
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	120.00	120.00	+
Subtotal before discount			6,000.80	
Percentage discount 20%			1,200.16	
Sub-total 1			4,800.64	
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00	
REAR BUMPER REVERSE SENSOR - SET <i>new</i>	1	280.00	280.00	20
REAR BUMPER UNDER COVER RH CLIPS - SET <i>new</i>	1	20.00	20.00	+
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	40.00	20
REAR END PANEL SEALANT <i>new</i>	1	80.00	80.00	+
REAR RH FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	40.00	80.00	+
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	15.00	15.00	+
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	40.00	40.00	+

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 92398048

TAX INVOICE

Repair Code : CLM16349

Date in : 01/07/2024

Vehicle Num. : SMG6101L

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72000329/LEB7100551

REAR TAILGATE NUMBER PLATE	1	25.00	25.00	+
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00	+
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	60.00	✓
Subtotal before discount			740.00	
Percentage discount 0%			0.00	
Sub-total 2			740.00	
Parts-total			5,540.64	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00	✓
To remove, reinstall tailgate windscreen	150.00	120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80.00	40
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	600
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00	400
To apply anti-rust chemical on repaired and replaced panel.	100.00	30
To remove, reinstall tailgate mechanism and check for function	80.00	60
Labour Total		2,490.00
Parts & Labour Total		8,030.64

*** This is a computer-generated document which requires no signature.***

page 3
the Repairer of the following
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/S 04/07/24
OBS