

Date: 02/07/2024

Vehicle No: SFC9600Y

Model: TESLA MODEL Y RWD

Chassis: LRWYHCF56PC892718-2023

Reg.Year: 2023

Third Party Insurer: AGI

Third Party Veh No: SKT4496R

Date of Accident: 01/07/2024

Estimator: TING AN

Surveyor:

*Not Authorised
Penny B4 pain
4 days
85714.92*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>R</i> \$1,219.62 ✓
2	REAR TAILGATE "TESLA" EMBLEM	1		<i>m</i> \$48.59 ✓
3	REAR TAILGATE INNER TRIM BOARD	1		<i>Pm</i> \$116.82 X
4	REAR BUMPER	1		<i>Bm</i> \$836.45 ✓
5	REAR BUMPER LOWER LIP	1		<i>nd/Lm</i> \$542.05 ✓
6	REAR BUMPER LOWER LIP CENTER COVER	1		<i>Sm</i> \$20.56 X
7	REAR BUMPER REFLECTOR LH	1		<i>cm</i> \$40.18 ✓
8	REAR BUMPER SIDE BRACKET LH	1		<i>R</i> \$5.60 X
9	REAR BUMPER REINFORCEMENT	1		<i>R</i> \$299.06 ✓
10	REAR BUMPER CENTER BRACKET	1		<i>cm</i> \$8.41 ✓
11	REAR BUMPER PARKING SENSOR	1		<i>Sm</i> \$158.87 X
12	REAR BUMPER PARKING SENSOR BRACKET	1		<i>R</i> \$6.54 X
13	REAR END PANEL	1		REPAIR
SUB TOTAL				\$3,302.75
LESS 10%				-\$330.28
PARTS TOTAL				\$2,972.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		\$100.00 <i>400m</i>
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>m</i> \$50.00 ✓
3	REAR BUMPER CLIPS	1		<i>m</i> \$50.00 ✓
4	PPF FOR AFFECTED AREAS	1	(Bill)	\$1,850.00 <i>1750</i>
S/N TOTAL				\$2,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Head office

6 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Signature:

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/07/2024
Vehicle No: SFC9600Y
Model: TESLA MODEL Y RWD
Chassis: LRWYHCFS6PC892718-2023
Reg.Year: 2023

Third Party Insurer: AGI
Third Party Veh No: SKT4496R
Date of Accident: 01/07/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

400/ \$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

640/ \$700.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

120/ \$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60/ \$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.

60/ \$120.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

30/ \$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$200.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

20/ \$120.00

LABOUR TOTAL \$2,230.00

TING AN

TOTAL \$7,252.48

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





INVOICE

BILL TO :

Name : Nelson Teo
Contact Number : 9362 9732

DATE : 5 June 2024

INVOICE : INV02598

Vehicle Make/Model/Colour : Tesla / Model 3 /White
Vehicle Registration Number : SKV 1332 P

Payment Mode : CASH / BANK/TT

DESCRIPTION	AMOUNT
Magnus Pro Optimum Paint Protection Film Full Exterior Gloss PPF package Centre Console PPF (FOC) Magnus Pro Nano-Ceramic Window Film Package N.A Nanonix Ceramic Coating N.A	\$ 4,980.00
Discount Booking Deposit Paid :	
 MAGNUS PRO WARRANTY :MP20240605250 Nanonix Warranty : Magnus Pro Paint Protection Film (PPF) Warranty 6 Years* against Bubbles, Cracking, and Delaminating *This warranty does not extend coverage to damage caused by normal wear and tear, environmental damages, road debris impact, accidents, collisions or intentional damage of any kind.	
Amount PAID :	\$ 4,980.00

GK Detailing Pte Ltd | 25 Kaki Bukit Rd 4, #06-59, Synergy @ Kaki Bukit, Singapore 417800
T: +65 9155 1806 / +65 9658 8936 | E: info@ace-gk.com



GK Detailing Pte Ltd | 25 Kaki Bukit Rd 4, #06-59, Synergy @ Kaki Bukit, Singapore 417800
T: +65 9155 1806 / +65 9658 8936 | E: info@ace-gk.com