

not Authorised
3/7/24
1/5 \$5000
wh ple Hk my
5 days

REPAIR ESTIMATE

Claim Type: Third Party Claim
Attn: Lonpac Insurance Bhd
Motor Claims Department
Owner: H CONCEPT ASIA PTE LTD
DOA: 1 Jul 2024

Date : 2 Jul 2024
Vehicle Num : SMN4742M
Make/Model : HONDA FIT 1.3GF CVT
Chassis # : GK33417742
Engine # : L13B3932234
Yr. Of Manu : 2019

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	REAR WINDSCREEN GLASS 5 hotterh	1	S\$ 1050.00 S\$	1,050.00
2	REAR WINDSCREEN MOULDING nel	1	S\$ 97.20 S\$	97.20
3	TAILGATE TOP PANEL panel 17	1	S\$ 385.00 S\$	385.00
4	THRID BRAKE LIGHT CRA	1	S\$ 195.00 S\$	195.00
5	TAILGATE 20/3ent	1	S\$ 880.50 S\$	880.50
6	TAILGATE NO.PLATE GARNISH ASSY 6u7	1	S\$ 224.70 S\$	224.70
7	TAILGATE NO.PLATE LAMP 17	2	S\$ 32.30 S\$	64.60
8	TAILGATE REFLECTOR R/L n/s n 10/50e 110.00	2	S\$ 182.60 S\$	365.20
9	TAILGATE EMBLEM (HONDA) 100 nel	1	S\$ 25.70 S\$	25.70
10	TAILGATE EMBLEM (FIT) 100	1	S\$ 35.00 S\$	35.00
11	TAILGATE SUPPORT STAY R/L 17	2	S\$ 143.60 S\$	287.20
12	TAILGATE INNER LINING ASSY 17	1	S\$ 165.00 S\$	165.00
13	TAILGATE INNER LINING CAP 17	10	S\$ 3.20 S\$	32.00
14	TAILGATE LOCK ASSY Daye	1	S\$ 157.20 S\$	157.20
15	TAILGATE WEATHERSTRIP su	1	S\$ 92.30 S\$	92.30
16	TAILGATE LAMP R/L Tail lamps 100 345 x 22 = 690	2	S\$ 657.00 S\$	1,314.00
17	REAR BUMPER 20/10e	1	S\$ 529.80 S\$	529.80
18	REAR BUMPER REINFORCEMENT NS	1	S\$ 150.90 S\$	150.90
19	REAR BUMPER GARNISH CENTER 17	1	S\$ 62.20 S\$	62.20
20	REAR BUMPER GARNISH TRIM R/L 17	2	S\$ 48.10 S\$	96.20
21	REAR BUMPER CLIPS nel	10	S\$ 3.20 S\$	32.00
22	REAR BUMPER SPACER R/L n/s n 10/50e	2	S\$ 22.70 S\$	45.40
23	REAR END PANEL 20/3ent	1	S\$ 398.60 S\$	398.60
24	REAR END PANEL INNER GARNISH 100	1	S\$ 68.30 S\$	68.30
25	REAR COMPARTMENT LID weipud	1	S\$ 230.90 S\$	230.90
26	REAR KEYLESS ENTRY WARNING BUZZER 17	1	S\$ 92.60 S\$	92.60
27	REAR LOCK ANTENNA antenna 17	1	S\$ 127.60 S\$	127.60
28	REAR FENDER R/L tender	2	S\$ 659.30 S\$	1,318.60
29	REAR FLOOR PANEL R	1	S\$ 875.00 S\$	875.00
30	REAR CHASSIS MEMBER R/L R	2	S\$ 580.00 S\$	1,160.00

Continue on next page...

Acknowledged by Repairer
Signature:
Date:

Amt S\$ 10,558.70
DISCOUNT: 20% S\$ 2,111.74
Subtotal S\$ 8,446.96

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: LIST ITEMS

31	REAR WINDSCREEN SEALANT <i>sealant</i>	1	80.00 S\$	80.00 <i>40</i>
32	REAR REVERSE SENSOR <i>SEN</i>	1	250.00 S\$	250.00 <i>X</i>
33	REAR ENDPANEL SEALANT <i>sealant</i>	1	80.00 S\$	80.00 <i>30</i>
1 set rear in-car camera Dye 350 S/N				Amt S\$ 410.00

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: LABOUR

34	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		S\$	1,800.00 <i>900</i>
35	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		S\$	1,800.00 <i>800</i>
	CHECK THE WIRING AND LIGHTING SYSTEM ON AFFECTED AND CONSISTENT AREAS		S\$	80.00 <i>20</i>
	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR		S\$	250.00 <i>120</i>
	TRANSFER AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE		S\$	80.00 <i>50</i>
	REMOVE, REPLACE, AND REINSTALL REAR INNER GARNISH, BOARDS, ROOF LINING, SEATS, CARPET, AND TRIMS TO ASSIST REPAIR		S\$	80.00 <i>60</i>
	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR <i>replace</i>			100.00 <i>30</i>
	APPLY RUST COATING CHEMICAL ON AFFECTED AND CONSISTENT AREAS AND PANELS		S\$	120.00 <i>60</i>
			S\$	120.00
			Amt S\$	4430.00



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal: S\$ 8,446.96
SPECIAL NETT ITEMS Subtotal S\$ 410.00
LABOUR Subtotal: S\$ 4,430.00
Total: S\$ 13,286.96

P. 4747.60
202
3798.08
420
2040
6258.08
202
5006