

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24070050/UPA3Q2**Date:** 18/11/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0006820  
**Claimant Vehicle No :** SNL836B **Insured Vehicle No :** PC5668K  
 Date of Loss: 29/06/2024 Nature of Claim: TP Claim No: MFL2024D0007681

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNL836B**  
 Make & Model: TOYOTA ALPHARD, 2.5 HYBRID SR C CVT (A) Engine No: 2AR2853920  
 Reg. Date: 05/06/2023 (Man. Year: 2022) Chassis No: AYH300152896  
 Colour: Black Odometer: 68023 km  
 Engine Capacity: 2493 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,273.95	2,439.97	2,833.98	53.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	950.00	1,600.00	62.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,823.95</b>	<b>3,389.97</b>	<b>4,433.98</b>	<b>56.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>(S\$)</b>	7,823.95	2,700.00	5,123.95	65.49
<b>+ GST 9.00/9.00% (S\$)</b>	704.16	243.00	461.16	65.49
<b>Nett Amount (S\$)</b>	<b>8,528.11</b>	<b>2,943.00</b>	<b>5,585.11</b>	<b>65.49</b>
<b>+ Car Rental (4.0 x S\$200.00/day) (S\$)</b>		800.00		
<b>(S\$)</b>		3,743.00		
<b>Liabe Amount (80.00%) (S\$)</b>		<b>2,994.40</b>		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>3,021.65</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,000.00</b>		

INSPECTION

Date of Assignment: 02/07/2024  
 Date Inspected: 02/07/2024 Inspected At: Ky Auto Pte Ltd (HQ)  
 25 KAKI BUKIT ROAD 4 SYNERGY@KB #05-23  
 Singapore 417800  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2024)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 HYBRID SR C CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNL836B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR LH	Badly Dented	2,960.40 FL	*2,685.10 FL
2	1		*REAR FENDER LH	Repair	3,250.00 FL	*- FL
3	1		*SLIDING MOULDING LH (CHROME)	Necessary	568.20 FL	*568.20 FL
4	1		*SLIDING DOOR LH CLIPS	Not Necessary	80.00 FL	*- FL
5	1		*SEALANT	Not Necessary	100.00 FS	*- FS
6	1		*TAPE	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	6,988.60 3,253.30
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,714.65 813.33
					Total Parts (S\$)	5,273.95 2,439.97
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & RENEW SIDE AFFECTED ACCIDENT AREAS	New	1,000.00	200.00
2	TO PUTTY SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS AND COATING	New	1,200.00	650.00
3	TO CONDUCT & RESET ECU DIAGNOSTIC PROGRAMME	New	200.00	80.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	150.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,550.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >