

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email: kyaautosg@gmail.com

Date: 02/07/2024

D.O.A 29/06/2024

SNL836B - Toyota Alphard
Damaged Area: Side Portion

Parts / Material :

Sliding Door LH	2685.10	\$	2,960.40 ✓
Rear Fender LH		\$	3,250.00 X
Sliding Moulding LH (Chrome)		\$	568.20 ✓
Sliding Door LH clips		\$	80.00 X

Parts: \$ 6,858.60
Less 25%: \$ 2,233.60
Total Parts: \$ 5,143.95

Special Net Items :

Sealant	11	\$	100.00 X
Tape	11	\$	30.00 X
Total S/N Parts :		\$	130.00

Labour :

To Remove & Renew Side Affected Accident Areas	\$	1,000.00 200
To Putty, Spray Paint on Rear Affected Accident Areas and contouring	\$	1,200.00 650
To conduct & reset ECU diagnostic programme	\$	200.00 80
To Check & Re-Connect all electrical wiring	\$	150.00 20
Total Labour :	\$	2,550.00

TOTAL PARTS : \$ 5,143.95
TOTAL S/N PARTS : \$ 130.00
TOTAL LABOUR : \$ 2,550.00
TOTAL REPAIR COST : \$ 7,823.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
L/S \$2700/

3 dys.

2/7/24

uh plus the y...

P-3283.3
252
3439.58
950
3389.9
202
2711