



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKK2

Section A - Accident Details	
Registration Number	SG6107A
Case Reference Number	BUS/06/23/7038
Registration Date	23/8/2019
Company Type	SMRT Buses Ltd
Make	
Model	MAN A95
Name of Driver	Zhang Chun
Type of Accident	Side Swipe
Accident Date and Time	29/6/2023 12:52 PM
Accident Reported Date and Time	3/7/2023 6:09 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG6107A - REAR RIGHT PORTION SLA708U (TP) - INSURED WITH AIG
Prepared Date and Time	10/7/2023 1:35 PM
Chassis Number	WMAA95ZZ0KF008854
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$354.00	\$0.00
Total Spare Part Cost	\$345.60	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,494.60	\$0.00
Lump Sum Total	\$1,500.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	10/07/2023 1:42 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/07/2023

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR					Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00						
Total Labour			\$795.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC					Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$354.00						
Total Spray Painting & Panel Beating			\$354.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC					Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013598	VE	36-25225-6004	REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	
6013599	VE	36-25103-6001	REVERSE LAMP	1.00	\$235.00	10.00	\$211.50	Replace	
6013482	Body	124-2-2-009-012	O/S FRP REAR LAMP	1.00	\$975.00	100.00	\$0.00	Repair	
Total					\$1,455.00		\$432.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									