

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 10.07.2023

MODEL: Toyota Prius

VEHICLE NO.: SHC1068M

SNF6131T

INSURANCE: CHINA TAIPING

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$503.04
	Rear Bumper Under Cover	1		\$654.96
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Side Brkt RH	1		\$112.70
	Rear Bumper Extension RH	1		\$232.00
	Rear Wheel Rim RH	1		\$1,570.55
	SUB TOTAL			\$3,095.25
	LESS 25%			\$773.81
	DISCOUNTED TOTAL			\$2,321.44
	Labour Charge			
	Panel Beating - Rear Fender Arch RH Etc		525	\$800.00
	Spray Painting Charge		500	\$600.00
	Check Lightings		X	\$40.00
	Remove/Refix Reverse Sensor		30	\$120.00
	TOTAL LABOUR			\$1,560.00
	ESTIMATE TOTAL			\$3,881.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
 WP 10/7/23 @ 430pm
 L/S Resurvey after repair
 Tanpin 1/8/2023
 5pm. 2 days

Date/Time: 10.07.2023 12:00 Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5903318

JC NO305560111

NUMBER: 7010045
COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
Singapore SINGAPORE 575717
P) 65508755 (O)
P)

REGN NO.: SHC1068M	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)10.	DATE/TIME IN 07.07.2023 11:20
YR OF MANU 20.09.2017	TARGET DATE
CHASSIS CODE JTDKB3FU503564191	COMPLETION DATE/TIME:


UNIT CARD NO.

JOB DESCRIPTION

cident Date: 07.07.2023
TURE: 3P 07.07.2023/C

NO LABOR CODE
0010 PB

DESCRIPTION
LUMPSUM REPAIR-SHC1068M-TP



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Idgement Slip

Exit Pass

o.: SHC1068M LIMITS

Vehicle No.: SHC1068M

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard