

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0737/2023/EQ
DATE : 3-Aug-23
WIP : 31718

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 04/08/2023.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. LEE CHEE KIONG
ADDRESS : 10B GERALD CRESCENT
SINGAPORE 799744
TELEPHONE : HP +65 96880863
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100271555-11
VEHICLE NO : **SKC 5437 U**
MODEL CODE : AUDI A6 C7 2.8 FSI MU
MODEL YEAR : 6/9/2011
ENGINE NO : CHV 004033
CHASSIS NO : WAUZZZ4G0BN025508
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Aug-23
PLACE OF ACCIDENT : GERALD DRIVE (OUTSIDE EXIT OF AMG CONSTRUCTIONS
& TOTALAND BUILDING MATERIALS)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 5437 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS FRONT DOOR.	\$ 4,000.00	2200 ✓
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,552.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 5437 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rebuilt</i>	1	\$ 3,187.00	✓
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 304.00	+
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 224.00	+
4	FRONT BUMPER GRILLE - RH <i>new</i>	1	\$ 181.00	+
5	FRONT BUMPER GUIDE PIECE - RH <i>?</i>	1	\$ 45.00	?
6	FRONT BUMPER BRACE - RH <i>?</i>	1	\$ 36.00	?
7	FRONT BUMPER TOP COVER <i>3 new</i>	1	\$ 145.00	+
8	CAUTION SIGN STICKER	1	\$ 17.00	+
9	AIR CONDITIONER STICKER	1	\$ 36.00	+
10	FRONT PARKING AID SENSOR - RH <i>new</i>	1	\$ 272.00	+
11	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 6.00	+
12	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,653.00	✓
13	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 47.00	+
14	FRONT FENDER AND DOOR STONE GUARD FILM - RH <i>new</i>	1	\$ 143.00	✓
15	FRONT FENDER BRACE - RH <i>?</i>	1	\$ 114.00	?
16	FRONT WHEEL HOUSING LINER - RH <i>?</i>	1	\$ 335.00	?
17	FRONT WHEEL SPOILER - RH <i>new</i>	1	\$ 311.00	+
18	BONNET <i>Regrind</i>	1	\$ 5,861.00	+
19	HEADLIGHT MOUNTING - RH <i>?</i>	1	\$ 140.00	?
20	GAS DISCHARGE LAMP HEAD LIGHT - RH <i>Cracked</i>	1	\$ 3,738.00	✓
SUB TOTAL SPARE PARTS		:	\$ 16,795.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 5437 U

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT			REMARKS
21	HEADLIGHT POWER MODULE <i>rel</i>	1	\$	690.00		<i>+</i>
22	GAS DISCHARGE LAMP CONTROL UNIT <i>rel</i>	1	\$	1,390.00		<i>+</i>
23	GAS DISCHARGE LAMP <i>rel</i>	1	\$	462.00		<i>+</i>
24	HEADLIGHT HOSE - RH <i>rel</i>	1	\$	102.00		<i>x</i>
25	HEADLIGHT COMPENSATING PIECE <i>green</i>	2	\$	94.00		<i>x</i>
26	HEADLIGHT ADJUSTMENT ELEMENT <i>green</i>	1	\$	54.00		<i>x</i>
27	LIFT CYLINDER <i>green</i>	1	\$	274.00		<i>+</i>
28	LIFT CYLINDER HOSE <i>green</i>	1	\$	44.00		<i>+</i>
29	RHS FRONT RIM <i>cut</i>	S/N		TBC		<i>✓</i>
30	SUNDRIES <i>?</i>		\$	400.00		<i>?</i>
TOTAL SPARE PARTS		:	\$	20,305.00		
TOTAL LABOUR CHARGES		:	\$	8,552.00		
GRAND TOTAL		:	\$	28,857.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: *Adrian*
: *04/08/23*

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *not authorised, 06 Days*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT