

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

25/06/2024

Vehicle No:

SKB5588Y

Brand & Model:

BMW 735i Pinnacle

Chassis/VIN No:

WBA12EH080CS69214

WIP#:

24941

Date:

1-Jul-24

Franchise:

BMW

Contact Person (Eurokars):

JOBI

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER	51 12 5A3DA91	1		\$ 1,492.15	\$ 1,492.15
2	REAR BUMPER TRIM	51 12 5A3DA96	1		\$ 362.20	\$ 362.20
3	TOWING COVER	51 12 5A3DA95	1			\$ 62.75
4	MOUNT FOR BUMPER LH	51 12 9464131	1			\$ 89.10
5	MOUNT FOR BUMPER RH	51 12 9464132	1			\$ 89.10
6	REAR BUMPER CENTER BRACKET	51 12 9464128	1			\$ 161.20
7	ADAPTER FOR PEDAL SENSOR	51 12 9464148	1			\$ 224.85
8	PROTECTIVE STRIP LH	51 12 9853579	1		\$ 83.15	\$ 83.15
9	PROTECTIVE STRIP RH	51 12 9853580	1		\$ 83.15	\$ 83.15
10	PROTECTIVE STRIP CENTER	51 12 9853569	1		\$ 135.40	\$ 135.40
11	KIT, MOUNT FOR BUMPER	51 12 5A3DA97	1		\$ 67.90	\$ 67.90
12	BRACKET SET FOR SENSOR	51 12 5A3DAA0	1		\$ 63.15	\$ 63.15
13	EXPANDING RIVET	07 14 7401727	6		\$ 15.90	\$ 15.90
14	EXPANDING NUT	63 12 1374075	2		\$ 1.10	\$ 1.10
15	REAR REINFORCEMENT	51 12 9464147	1			\$ 1,040.85
16	SEAL FOR REINFORCEMENT	51 12 5A7CEA6	2			\$ 9.40
17	SENSOR GASKET	66 20 9283203	6		\$ 33.30	\$ 33.30
18	REAR REFLECTOR LH OUTER	63 14 9464195	1			\$ 46.90
19	REAR REFLECTOR RH OUTER	63 14 9464196	1			\$ 46.90
20	REAR REFLECTOR INNER LH	63 14 5A097B1	1			\$ 46.90
21	REAR REFLECTOR INNER RH	63 14 5A097B2	1			\$ 46.90
22						\$ -

Parts Price	\$ 2,337.40	\$ 4,202.25
Sub-Total (Parts Price)	\$ 2,337.40	\$ 4,202.25

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE DAMAGED REAR BUMPER, REAR BUMPER REINFORCEMENT & ALL ACCIDENT BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 850.00	\$ 2,550.00
2	TO RESPRAY REAR BUMPER, REAR BUMPER LOWER TRIM	\$ 1,880.00	\$ 2,100.00

3	TO SUPPLY REAR LICENCE PLATE WITH CASING	\$ 150.00	\$ 150.00
4	TO TRANSFER THE REAR BUMPER SENSORS.	\$ 250.00	\$ 500.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 350.00	\$ 600.00
7	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ 3,650.00 \$ 6,200.00

	REVISED	PRICE
Parts Price	\$ 2,337.40	\$ 4,202.25
Labour Price	\$ 3,650.00	\$ 6,200.00
Total (Initial Estimate)	\$ 5,987.40	\$ 10,402.25
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ 5,987.40	\$ 10,402.25
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ 5,987.40	\$ 10,402.25
GST 9%	\$ 538.87	\$ 936.20
GRAND TOTAL	\$ 6,526.27	\$ 11,338.45