

ASSIGNMENT

From: _____ Date: _____
 Estin: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To In _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy: _____
 Claim: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP 1st Cap

MV: 86K

PV: 19.1K

Nett: 16.9K.

Veh No: SMX45787 Yr Regn: 2016 Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 C.D. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 113637 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM66J1072G0226231

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Lgssc

Front

R/Bal. 26 mm

L/Bal. 26 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 03/07/24

Survey held at

HD Perfect

Des. of Damages: Frt / Rear / O/S / WS / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

COE Expiry

Estimate given during: Yes (✓)
 1st Survey: No ()

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee:

Transportation:

_____ \$ + R.S. _____ \$

Photos

Others

Report Form:

Report Form: _____

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 01.07.2024

TO : MS FIRST CAP MOTOR CLAIMS DEPTS
VEHICLE NO : SMX4578T
MODEL : MAZDA 6
DATE OF ACCIDENT : 28.06.2024
TIME OF ACCIDENT : 23:35 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delhd</i>	1	\$ 1,211.90	\$ 1,211.90
2	FRONT BUMPER (TOP) <i>new</i>	1	\$ 471.00	\$ 471.00
3	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 77.00	\$ 77.00
4	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 31.80	\$ 31.80
5	FRONT BUMPER FOGLAMP <i>Cond new</i>	2	\$ 736.80	\$ 1,473.60
6	FRONT BUMPER FOGLAMP MOULDING <i>new</i>	2	\$ 101.90	\$ 203.80
7	FRONT BUMPER FOGLAMP COVER GARNISH <i>new</i>	2	\$ 22.70	\$ 45.40
8	FRONT BUMPER TOP SUPPORT GARNISH <i>new</i>	1	\$ 189.20	\$ 189.20
9	FRONT BUMPER BRACKET <i>new</i>	2	\$ 39.70	\$ 79.40
10	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 27.30	\$ 54.60
11	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 579.60	\$ 579.60
12	FRONT BUMPER SPONGE <i>new</i>	1	\$ 160.00	\$ 160.00
13	FRONT BUMPER UNDER COVER GARNISH <i>new</i>	1	\$ 117.10	\$ 117.10
14	FRONT FENDER LH <i>Distorted</i>	1	\$ 383.70	\$ 383.70
15	FRONT FENDER INNER COWLING <i>Delhd</i>	2	\$ 170.00	\$ 340.00
16	FRONT WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 1,668.00	\$ 1,668.00
17	HEADLAMP (LED) <i>LH int</i>	2	\$ 3,369.80	\$ 6,739.60
18	FRONT GRILLE <i>Also new Cond.</i>	1	\$ 120.60	\$ 120.60
19	FRONT GRILLE SIDE CHROME <i>new</i>	2	\$ 144.60	\$ 289.20
20	FRONT GRILLE LOGO <i>new</i>	1	\$ 49.00	\$ 49.00
21	FRONT GRILLE MOULDING <i>new</i>	8	\$ 48.80	\$ 390.40

3369.80

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMX4578T**
 MODEL : **MAZDA 6**
 DATE OF ACCIDENT : 28.06.2024
 TIME OF ACCIDENT : 23:35 HOURS

22	FRONT GRILLE MOULDING (LOWER) <i>new</i>	2	\$ 79.80	\$ 159.60	+
23	BONNET <i>Buckled</i>	1	\$ 1,264.50	\$ 1,264.50	✓
24	BONNET INNER RUBBER	1	\$ 87.10	\$ 87.10	+
25	BONNET STOPPER	2	\$ 21.40	\$ 42.80	+
26	BONNET HINGE	2	\$ 46.90	\$ 93.80	+
27	BONNET LOCK	1	\$ 186.20	\$ 186.20	+
28	BONNET INSULATOR	1	\$ 183.30	\$ 183.30	+
29	BONNET LOCK BRACE PANEL	1	\$ 67.00	\$ 67.00	+
30	FRONT SUPPORT PANEL (TOP)	1	\$ 137.00	\$ 137.00	+
31	FRONT SUPPORT PANEL COVER GARNISH <i>2nd</i>	1	\$ 143.00	\$ 143.00	+
32	FRONT SUPPORT PANEL LOWER GARNISH <i>1st</i>	1	\$ 89.00	\$ 89.00	+
33	FRONT WIRE HARNESS <i>new</i>	1	\$ 1,281.91	\$ 1,281.91	+
34	RADIATOR SUPPORT PANEL <i>new could</i>	1	\$ 493.20	\$ 493.20	✓
35	RADIATOR <i>new</i>	1	\$ 1,015.50	\$ 1,015.50	+
36	RADIATOR CENTER AIR GUARD <i>2nd</i>	1	\$ 373.30	\$ 373.30	+
37	RADIATOR RUBBER MOUNTING <i>new</i>	4	\$ 18.00	\$ 72.00	+
38	AIR CON CONDENSER AIR GUARD	2	\$ 76.40	\$ 152.80	+
39	AIRCON CONDENSER <i>new</i>	1	\$ 1,116.20	\$ 1,116.20	+
40	AIR CON CONDENSER MOUNTING RUBBER <i>new</i>	1	\$ 14.00	\$ 14.00	+
41	FRONT ABS SENSOR	1	\$ 396.00	\$ 396.00	+
42	FRONT SHOCK ABSORBER LH	1	\$ 398.00	\$ 398.00	+
43	FRONT KNUCKLE ARM LH <i>new</i>	1	\$ 596.00	\$ 596.00	+
44	FRONT KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 215.00	\$ 215.00	+
45	FRONT LOWER ARM LH	1	\$ 527.00	\$ 527.00	+
46	FRONT STEERING RACK AND PINION	1	\$ 1,958.30	\$ 1,958.30	+

TOTAL PRICE \$ 25,737.41
 LESS 20% \$ 5,147.48
SUB TOTAL PRICE \$ 20,589.93

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER TOP SUPPORT GARNISH CLIP (SET) <i>2nd</i>	1	\$ 50.00	\$ 50.00
4	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>1st</i>	1	\$ 50.00	\$ 50.00

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMX4578T**
 MODEL : **MAZDA 6**
 DATE OF ACCIDENT : 28.06.2024
 TIME OF ACCIDENT : 23:35 HOURS

5	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
6	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
7	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
8	BONNET WEATHERSTRIP CLIP (OUTER) (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
9	FRONT SUPPORT PANEL COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
10	FRONT SUPPORT PANEL LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
11	RADIATOR SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
12	RADIATOR COOLANT <i>new</i>	1	\$ 60.00	\$ 60.00	<i>40</i>

TOTAL \$ 570.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>+</i>
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>+ 60</i>
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>+ 60</i>
8	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>+</i>
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>+</i>
7	TO PRESS FRONT WHEEL BEARING	\$ 80.00	<i>+</i>
8	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>+</i>

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMX4578T**
MODEL : **MAZDA 6**
DATE OF ACCIDENT : 28.06.2024
TIME OF ACCIDENT : 23:35 HOURS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL

\$5,470.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 21,159.93
TOTAL LABOUR COST : \$ 5,470.00
TOTAL REPAIR COST : \$ 26,629.93

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: