


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 01.07.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMX4578T**
MODEL : **MAZDA 6**
DATE OF ACCIDENT : 28.06.2024
TIME OF ACCIDENT : 23:35 HOURS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delid</i>	1	\$ 1,211.90	\$ 1,211.90
2	FRONT BUMPER (TOP) <i>new</i>	1	\$ 471.00	\$ 471.00
3	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 77.00	\$ 77.00
4	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 31.80	\$ 31.80
5	FRONT BUMPER FOGLAMP <i>new</i>	2	\$ 736.80	\$ 1,473.60
6	FRONT BUMPER FOGLAMP MOULDING <i>new</i>	2	\$ 101.90	\$ 203.80
7	FRONT BUMPER FOGLAMP COVER GARNISH <i>new</i>	2	\$ 22.70	\$ 45.40
8	FRONT BUMPER TOP SUPPORT GARNISH <i>new</i>	1	\$ 189.20	\$ 189.20
9	FRONT BUMPER BRACKET <i>new</i>	2	\$ 39.70	\$ 79.40
10	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 27.30	\$ 54.60
11	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 579.60	\$ 579.60
12	FRONT BUMPER SPONGE <i>new</i>	1	\$ 160.00	\$ 160.00
13	FRONT BUMPER UNDER COVER GARNISH <i>new</i>	1	\$ 117.10	\$ 117.10
14	FRONT FENDER LH <i>Distorted</i>	1	\$ 383.70	\$ 383.70
15	FRONT FENDER INNER COWLING <i>Delid</i>	2	\$ 170.00	\$ 340.00
16	FRONT WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 1,668.00	\$ 1,668.00
17	HEADLAMP (LED) <i>LA int</i>	2	\$ 3,369.80	\$ 6,739.60
18	FRONT GRILLE <i>new</i>	1	\$ 120.60	\$ 120.60
19	FRONT GRILLE SIDE CHROME <i>new</i>	2	\$ 144.60	\$ 289.20
20	FRONT GRILLE LOGO <i>new</i>	1	\$ 49.00	\$ 49.00
21	FRONT GRILLE MOULDING <i>new</i>	8	\$ 48.80	\$ 390.40

3369.80

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMX4578T**
 MODEL : **MAZDA 6**
 DATE OF ACCIDENT : 28.06.2024
 TIME OF ACCIDENT : 23:35 HOURS

22	FRONT GRILLE MOULDING (LOWER) <i>new</i>	2	\$ 79.80	\$ 159.60	+
23	BONNET <i>Buckled</i>	1	\$ 1,264.50	\$ 1,264.50	✓
24	BONNET INNER RUBBER <i>2</i>	1	\$ 87.10	\$ 87.10	+
25	BONNET STOPPER	2	\$ 21.40	\$ 42.80	+
26	BONNET HINGE	2	\$ 46.90	\$ 93.80	+
27	BONNET LOCK <i>XHP</i>	1	\$ 186.20	\$ 186.20	+
28	BONNET INSULATOR <i>new</i>	1	\$ 183.30	\$ 183.30	+
29	BONNET LOCK BRACE PANEL	1	\$ 67.00	\$ 67.00	+
30	FRONT SUPPORT PANEL (TOP)	1	\$ 137.00	\$ 137.00	+
31	FRONT SUPPORT PANEL COVER GARNISH <i>2HP</i>	1	\$ 143.00	\$ 143.00	+
32	FRONT SUPPORT PANEL LOWER GARNISH <i>1HP</i>	1	\$ 89.00	\$ 89.00	+
33	FRONT WIRE HARNESS <i>new</i>	1	\$ 1,281.91	\$ 1,281.91	+
34	RADIATOR SUPPORT PANEL <i>new could</i>	1	\$ 493.20	\$ 493.20	✓
35	RADIATOR <i>new</i>	1	\$ 1,015.50	\$ 1,015.50	+
36	RADIATOR CENTER AIR GUARD <i>2HP</i>	1	\$ 373.30	\$ 373.30	+
37	RADIATOR RUBBER MOUNTING <i>new</i>	4	\$ 18.00	\$ 72.00	+
38	AIR CON CONDENSER AIR GUARD	2	\$ 76.40	\$ 152.80	+
39	AIRCON CONDENSER <i>new</i>	1	\$ 1,116.20	\$ 1,116.20	+
40	AIR CON CONDENSER MOUNTING RUBBER <i>new</i>	1	\$ 14.00	\$ 14.00	+
41	FRONT ABS SENSOR <i>2</i>	1	\$ 396.00	\$ 396.00	+
42	FRONT SHOCK ABSORBER LH	1	\$ 398.00	\$ 398.00	+
43	FRONT KNUCKLE ARM LH <i>new</i>	1	\$ 596.00	\$ 596.00	+
44	FRONT KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 215.00	\$ 215.00	+
45	FRONT LOWER ARM LH	1	\$ 527.00	\$ 527.00	+
46	FRONT STEERING RACK AND PINION	1	\$ 1,958.30	\$ 1,958.30	+

7183.70
574696

TOTAL PRICE \$ 25,737.41
 LESS 20% \$ 5,147.48
SUB TOTAL PRICE \$ 20,589.93

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	FRONT BUMPER TOP SUPPORT GARNISH CLIP (SET) <i>2HP</i>	1	\$ 50.00	\$ 50.00	+
4	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>1HP</i>	1	\$ 50.00	\$ 50.00	+

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMX4578T**
 MODEL : **MAZDA 6**
 DATE OF ACCIDENT : 28.06.2024
 TIME OF ACCIDENT : 23:35 HOURS

5	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
6	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
7	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
8	BONNET WEATHERSTRIP CLIP (OUTER) (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
9	FRONT SUPPORT PANEL COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
10	FRONT SUPPORT PANEL LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
11	RADIATOR SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
12	RADIATOR COOLANT <i>new</i>	1	\$ 60.00	\$ 60.00	<i>40</i>
			<i>100</i> TOTAL	\$ 570.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>+</i>
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>+ 60</i>
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>+ 60</i>
8	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>+</i>
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>+</i>
7	TO PRESS FRONT WHEEL BEARING	\$ 80.00	<i>+</i>
8	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>+</i>

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMX4578T**
MODEL : **MAZDA 6**
DATE OF ACCIDENT : 28.06.2024
TIME OF ACCIDENT : 23:35 HOURS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

1580

TOTAL

\$5,470.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 21,159.93
TOTAL LABOUR COST : \$ 5,470.00
TOTAL REPAIR COST : \$ 26,629.93

Adrian King
L/S 03/07/24.
06 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

total: 7426.96

L/S: 5950

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: