

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

TP111
Daphne

Contact : 97314140

TAX INVOICE

Repair Code : CLM16350

Date in : 02/07/2024

Vehicle Num. : SMQ8259A

Model : TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng# : NHP1707181269/1NZR808197

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delhd</i>	1	750.00	750.00 <i>485</i>
REAR BUMPER CENTER PROTECTOR GARNISH <i>Delhd</i>	1	207.00	207.00 <i>-</i>
REAR BUMPER REFLECTOR L/R <i>New</i>	2	85.00	170.00 <i>+</i>
REAR BUMPER SIDE PROTECTOR GARNISH L/R <i>New</i>	2	151.00	302.00 <i>+</i>
REAR BUMPER SIDE RETAINER L/R <i>New</i>	2	90.00	180.00 <i>+</i>
REAR BUMPER TOW HOOK COVER <i>New</i>	1	25.00	25.00 <i>+</i>
REAR END OUTER PANEL <i>Detctd</i>	1	533.60	533.60 <i>✓</i>
REAR END PANEL KEY ANTENNA SENSOR <i>Crnkhd</i>	1	127.00	127.00 <i>-</i>
REAR END PANEL TOP GARNISH <i>Crnkhd</i>	1	207.00	207.00 <i>✓</i>
REAR TAILGATE <i>Detctd</i>	1	1131.90	1,131.90 <i>✓</i>
REAR TAILGATE 'LOGO' EMBLEM <i>New</i>	1	79.40	79.40 <i>-</i>
REAR TAILGATE HINGES L/R <i>New</i>	2	78.00	156.00 <i>+</i>
REAR TAILGATE INNER PULL HANDLE <i>New</i>	1	38.00	38.00 <i>+</i>
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>New</i>	2	19.00	38.00 <i>+</i>
REAR TAILGATE INNER TRIM BOARD <i>New</i>	1	208.00	208.00 <i>+</i>
REAR TAILGATE MECHANISM LOCK <i>Repd</i>	1	265.00	265.00 <i>✓</i>
REAR TAILGATE WEATHER STRIP <i>Gr</i>	1	385.00	385.00 <i>✓</i>
REAR TAILGATE WINDSCREEN MOULDING L/R <i>New</i>	2	45.00	90.00 <i>✓</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 97314140

TAX INVOICE

Repair Code : CLM16350

Date in : 02/07/2024

Vehicle Num. : SMQ8259A

Model : TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng# : NHP1707181269/1NZR808197

REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) <i>new</i>	2	45.00	90.00 ✓
<i>3610.90</i>		Subtotal before discount	4,982.90
<i>2708.17</i> Percentage discount 25%			1,245.73
	Sub-total 1		3,737.18
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	250.00 <i>200</i>
REAR END PANEL TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 <i>20</i>
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	50.00 <i>+</i>
REAR TAILGATE NUMBER PLATE <i>2 new</i>	1 <i>310</i>	25.00	25.00 <i>+</i>
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	50.00 <i>+</i>
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 <i>+</i>
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	60.00 ✓
	Subtotal before discount		545.00
Percentage discount 0%			0.00
	Sub-total 2		545.00
	Parts-total		4,282.18

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

80.00 ✓

To remove, reinstall tailgate windscreen

~~150.00~~ *120*

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 97314140

TAX INVOICE

Repair Code : CLM16350

Date in : 02/07/2024

Vehicle Num. : SMQ8259A

Model : TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng# : NHP1707181269/1NZR808197

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.
To remove, reinstall tailgate mechanism and check for function

80.00 60
1,000.00 60
1,000.00 60
80.00 60
80.00 60

1580

Labour Total

2,470.00

Parts & Labour Total

6,752.18

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adm
1/s 03/07/24
06 days

total: 4598.17

1/s: 3.6K ✓