# ASS, REG. BY: Tayph - | NEF: CS | FC | 24060037 | Tnp3

ASSIGNMENT Veh No: SG 5952H From: Estimated Cost: Type: M.Car / M.Cycle (Bus / Van / Lorry / Taxl / Prime Mover / OD TP/WS/TP RES/OD RES/EVA/INV/MV Truck / Traller or To Inspect Vehicle No: MAN A95 0000 at Workshop m/s Colour A/G: Insured / Std / NI / NA Sp.Reading T/Radio: Insured / Std / NI / NA Insured: Eng/No: Policy No. C/No: Claims No. Gen. Cond: 600d / Fair / Poor / Burnt Sum Insured: Excess: Steering: Inorder / Jammed / Leaked / Burnt or (Client's Record) Brake; Inforder / Jammed / Leaked / Burnt or 50k Make of Veh: Modl: (NII) S/Rim / STD A/Rim or Tyre Size: (Policy Condition) Remark: The veh had commenced its O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. Firenza TOYO / YOKO or Bal. or Market Value: Front Rear IDAC Accident Rport Consistent?: Yes or No R/Bal. R/Bal. GIA / PR Seen: Consistent?: Yes or No L/Bal. Est. Repairs: 80 days Res.: Yes or No D.O.A. D.O.I. Lum Sum: 3 Val.: Yes or No Survey held at Des. of Damages : Frt / Rear / O/S / N/S / U/G / Rooftop or 1 REP. 1 24 HRS Same IN / OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Please refer attached, COR \$205,391.25, 80 days. (red, \$60770.65, 23%) Date/Time, File Pass to? : Prell. Report Days Of Repair: 80 : Final Report Resurvey No. of Trip: Survey Fee: Dale/Time, File Return to? Transportation: Add Fee: :Site Insp (\$ \_S+RS\_\_SI : Interview (\$ Popular : Tech. Invs (\$ Others Lump Sum/LB.E.CF Weellend (\$ TOTAL

# **ESTIMATED ACCIDENT REPAIR COST**



Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	13:50HRS
ACCIDENT DATE	06-Jun-24
BUS CAPTAIN NAME	LIM YONG SENG
THIRD PARTY CLAIM AGAINST	MS First Capital Insurance Ltd

BUS REGISTRATION NUMBER	SG5952H
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

### SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	LOWER FRONT WINDSCREEN FW3	Lrav	\$ 4,375.00
2	DESTINATION GLASS	we/	\$ 2,375.00
3	NS FRONT HEAD LAMP	cm/	\$ 1,875.00
4	NS LOWER WINDOW GLASS L8	cma/	\$ 750.00
5	NS LOWER WINDOW GLASS L9	one/	\$ 750.00
6	NS LOWER WINDOW GLASS L10	cra-	\$ 750.00
7	NS LOWER WINDOW GLASS L11	cna	\$ 750.00
8	NS LOWER WINDOW GLASS L12	cuA/	\$ 750.00
9	NS UPPER DECK BODY PANEL (LONG) L1	61/	\$ 13,750.00
10	NS SIDE VERTICAL PANEL FRP L2	dd/	\$ 950.00
11	INTERIOR WALL FORMICA LL2 (AFTER EXIT DOOR TO REAR)	(N)	\$ 450.00
12	NS REAR SIDE BODY PANEL L9	b+/	\$ 625.00
13	NS REAR SIDE BODY PANEL L10	4/	\$ 550.00
14	NS REAR SIDE BODY PANEL L11	h1/	\$ 550.00
15	NS EXTERIOR SIDE WALL 4446MM	ht/	\$ 11,250.00
16	NS REAR ENGINE DOOR	ht/	\$ 800.00
17	NS REAR ENGINE DOOR FRAME - No	?	\$ 750.00
18	WHEELARCH TRIM FRP	cra/	\$ 500.00
19	EXTERIOR HANDICAP BUTTON	ut/	\$ 875.00
20	EXIT DOOR 3 PILLAR (120MM) 2783MM	b1/	\$ 2,125.00
21	EXIT DOOR 4 PILLAR (120MM) 2783MM	b1/	\$ 2,125.00
22	PILLAR REPAIR KIT 1 FOR 57947	NC/	\$ 150.00
23	NS WINDOW 5 PILLAR (100MM) 2085MM	61-	\$ 1,375.00
24	PILLAR REPAIR KIT 4 FOR 58081	we !	\$ 300.00
25	L CORNER R120 ANGLE	nel/	\$ 225.00
26	WINDOW ALUMINUM FRAME (40MM) 1375MM	26/	\$ 700.00
27	TOGGLE M10	w.c	\$ 100.00
28	TOGGLE M8	wl-	\$ 150.00

29	SPLIT WASHER SS	nec/	\$ 2.50
30	HEX BOLT M8 X 25	nei/	\$ 5.00
31	FLAT WASHER M8 X 1.8 X 23	wc/	\$ 7.50
32	UPPER DECK ALUMINUM HORIZONTAL PILLAR (CANTILEVER) 9.7M	7.	\$ 12,000.00
33	NS INTERIOR WINDOW PILLAR COVER 2	dis	\$ 475.00
34	NS INTERIOR WINDOW PILLAR COVER 3	lis/	\$ 475.00
35	NS INTERIOR WINDOW PILLAR COVER 4	25	\$ 475.00
36	NS INTERIOR WINDOW PILLAR COVER 5	dis	\$ 475.00
37	NS INTERIOR FRONT WINDOW HORIZONTAL CAPPING	67	\$ 475.00
38	WINDOW RUBBER SEAL GASKET	Ne (	\$ 300.00
39	NS REAR MODESTY PANEL	cra	\$ 700.00
40	OS REAR MODESTY PANEL	ر میں	\$ 700.00
41	INTERIOR NS DOOR 3 ACRYLIC PANEL	Cra/	\$ 1,425.00
42	INTERIOR ROOM LIGHT ACRYLIC COVER A151 (90.3 X2.8) (3.5M)	? photo.	\$ 300.00
43	NS REAR STANCHION POLE	b+/	\$ 1,875.00
44	OS REAR STANCHION POLE	64/	\$ 1,875.00
45	PAX DOUBLE SEAT WITH STANDARD SEAT LEG & WALL BRACKET	bror	\$ 3,000.00
46	NS STANCHION POLE DOWNSTAY SHORT	b+/	\$ 950.00
47	BASE JOINT VERTICAL MOUNT ID38MM	b+/	\$ 125.00
48	BASE JOINT GREY ID38MM	b) -	\$ 75.00
49	BASE JOINT RUBBER ID35.5MM	bt-	\$ 77.50
50	TEE JOINT ID35MM	ht-	\$ 950.00
51	UPPER DECK NS NO.3 HAND POLE	カナー	\$ 1,050.00
52	BELDEN CABLE 9841	?	\$ 200.00
53	ENTRANCE DOOR FRAME RUBBER NO.1 & 2	ant.	\$ 420.00
54	REAR DOOR FRAME CAPPING TOP, LH & RH COMPLETE SET	his	\$ 875.00
55	UPPER FRONT EDS FRAME	bt/	\$ 2,250.00
56	UPPER FRONT EDS CONSOLE FRP	cus/	\$ 1,375.00
57	UPPER FRONT EDS CONSOLE DOOR FRP	cun/	\$ 450.00
58	ENTRANCE DOOR FULL KIT	bt/	\$ 28,000.00
59	ENTRANCE DOOR 1 & 2 ASSY COMPLETE SET	b+/	\$ 12,500.00
60	ENTRANCE DOOR RIGHT BAR	bt/	\$ 1,325.00
61	ENTRANCE DOOR LEFT BAR	bt/	\$ 1,325.00
62	EXIT DOOR NO. 3 & 4 ASSY COMPLETE SET INCLUDE SELFPLATE	bt/	\$ 49,000.00
63	NS REAR WHEEL RIM	b+-	\$ 4,550.00
64	NS REAR WHEEL RIM COVER 22	bt	\$ 220.00
65	NS REAR TAG WHEEL RIM COVER	6t/	\$ 412.50
66	MAN LOGO LABEL	Nel/	\$ 160.00
67	TYRE 275/70R 22.5	tu	\$ 1,500.00

68	SEALANT BLACK BOSTIK 600ML	MC/	\$ 1,312.50
69	EURO 6 EMBLEM PLATE	rec/	\$ 42.50
70	FAMWES STICKER	nel-	\$ 25.00
71	ENTRANCE STICKER	vel-	\$ 12.50
72	EXIT STICKER	Net /	\$ 12.50
73	TTS LOGO STICKER (BIG)	nel-	\$ 70.00
74	NET / VISA STICKER	nec/	\$ 45.00
75	TTS LOGO STICKER (SMALL)	rel/	\$ 37.50
76	EMERGENCY STICKER	vel-	\$ 25.00
77	PLEASE FOLD YOUR STROLLER IF THE BUS IS CROWDED STICKER	rec/	\$ 37.50
78	EXIT DOOR CONSOLE FRP ASSY	bvo/	\$ 2,050.00
79	UPPER DECK INTERIOR NS SIDE WALL FORMICA	Cva/	\$ 1,000.00
80	UPPER DECK INTERIOR NS SIDE WALL ALUMINIUM PANEL	bt/	\$ 1,700.00
		•	
		9% GST	\$ 17,046.00
		PARTS TOTAL COST	\$ 206,446.00

# **ESTIMATED ACCIDENT REPAIR COST**



#### SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
1) DESTINATION GLASS (1 LOT) 2) LOWER FRONT WINDSCREEN (1 LOT) 3) NS LOWER DECK SIDE WINDOW L8 TO L12 (5 PIECES) 4) NS INTERIOR WINDOW CAPPING 2, 3, 4, 5 (4 PIECES) 5) INTERIOR NS & OS REAR MODESTY PANEL (1 LOT) 6) INTERIOR NS & OS STANCHION POLE (1 LOT) 7) NS UPPER DECK BODY PANEL (LONG) (1 LOT)		
8) UPPER DECK ALUMINUM HORIZONTAL PILLAR (CANTILEVER) 9.7M 1 (1 LOT) 9) NS LOWER REAR BODY PANEL(SHORT) (1 LOT) 10) NS REAR SIDE PANEL L9, L10, L11 (3 PIECES) 11) NS REAR ENGINE DOOR PANEL (1 LOT) 12) FRONT EDS FRAME (1 LOT) 13) ENTRANCE DOOR ASSY 1 & 2 (1 LOT) 14) EXIT DOOR SYSTEM (1 LOT) 15) EXIT DOOR LEAF 3 & 4 (1 LOT) 16) REAR DOOR FRAME CAPPING LH & RH SET (1 LOT)		\$ 39,000.00
17) NS FRONT LAMP ASSY (1 LOT) 18) EXIT DOOR FRAME PILLAR 3 & 4 (1 LOT) 19) NS INTERIOR LIGHT COVER (1 LOT) 20) UPPER DECK FRONT EDS COMPARTMENT DOOR (1 LOT) 21) UPPER DECK PAX 2 SEATER FRAME & LEG (3 SETS) 22) UPPER DECK WALL PANEL & FORMICA (1 LOT) 23) NS REAR TYRE, RIM ASSY & RIM COVER (1 LOT) 24) NOBE BCV 4 CABLE (1 LOT)		936400
REMOVE, REPLACE & CONFIGURATION		
1) NS REAR TOP CCTV CAMERA 2) NOBE SYSTEM 3) FRONT, SIDE & REAR EDS SYSTEM	3250	\$ 3,900.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :-		
1) FRONT CCTV MONITOR HOUSING FRP 2) NS FRONT PILLAR 3) NS FRONT CORNER DOME 4) UPPER DECK FRONT EDS COMPARTMENT FRP 5) NS MIRROR ADJUSTING CABLE	1950	\$ 3,250.00
SPRAY PAINTING :-		
1) FRONT DOME 2) FRONT PANEL 3) FRONT SERVICE HATCH 4) FRONT BUMPER 5) NS & OS FRONT LAMP COVER 6) NS UPPER DECK SIDE BODY PANEL FRONT TO REAR X 4 7) NS VERTICAL PANEL 8) NS LOWER DECK FRONT PANEL L3, L4, L5, L6 & L7 9) NS LOWER DECK REAR PANEL L9, L10, 11, L12, L14 L15	3250	\$ 5,760.00

### **ESTIMATED ACCIDENT REPAIR COST**



Co. / GST Reg No. 201419417K

POLISHING & RESEAL :- NS LOWER DECK SIDE WINDOW L13 & L14 (1 LOT)	975	\$ 1,300.00
INTERIOR CLEANING :  1)REMOVER GLASS DEBRIS  2)DEEP CLEAN BUS INTERIOR	975	\$ 1,300.00
SPRAY PAINTING \$640 PER PANEL	9% GST	\$ 4,905.90
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST	\$ 59,415.90

#### SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	\$300.00
-------------------	----------

#### SECTION 4: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

			DATE IN	6-Jun-2024
			DATE & TIME SURVEY	
			DATE OUT	
BUS TYPE (SD / DD)	DD		TOTAL NUMBER OF DAYS	
	LOSS OF USE COS	Т		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Taufilm 97495M9 plp lasmy before paint taufilm C lehanto im 8 Odays

SUMMARY				
SECTION NO.	COST			
1	\$ 206,446.00			
2	\$ 59,415.90			
3	\$ 300.00			
4	\$ -			
TOTAL	\$ 266,161.90			