

ASS. REC. BY:

REF: CT21

CS/CT124070056/KNP3

C

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s JD

of 194N

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 223K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PNN 94915 Yr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A) Wagon

Make: Toy Vaux C.G. 1797

Colour: M.P. White A/C: Insured / Std / Nil / NA

Sp. Reading: 42517 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: ZWR90 0135298

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 205/55R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 5 mm R/Bal. 7 mm

L/Bal. 5 mm L/Bal. 7 mm

D.O.A. 29/6/24 D.O.I. 3/7/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/7 11:30 @ 10.000. Caber (Red, \$ 17752.05, 62%)

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

1)

: Final Report

Date/Time, File Return to?

Transportation:

2)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

) \$ - RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

# JD MOTORSPORTS

JD MOTORSPORTS PTE LTD  
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

Not Authorized  
L1 Rm @ 10,600p  
Permy After Paint  
6 days

DATE : 02/07/2024  
VEHICLE : SNN9491S  
MAKE/MODEL : TOYOTA / VOXY  
CHASSIS NO : ZWR90-0135298  
MILLAGE : 42517KM  
TYRE SIZE : 205/55/R17  
DOA : 26/06/2024

LIST ITEM

01 PC	TAIL GATE	1984.20	Bj	\$	2,281.24	✓
02 PC	TAIL GATE HINGES @ \$112.74		R	\$	225.48	X
02 PC	TAIL GATE ABSORBER @ \$335.99		R	\$	671.98	X
01 PC	TAIL GATE TRIMBOARD		Bu	\$	<del>700.00</del>	✓ 890.00
01 PC	780.00 TAIL GATE OUTER GARNISH		ms	\$	809.06	✓
02 PC	TAIL GATE OUTER LAMP @ \$1127.36	0771-20	cut	\$	2,254.72	✓
01 PC	TAIL GATE OUTER SWITCH			\$	365.02	X SVC
01 PC	TAIL GATE EMBLEM (HYBRID)		na	\$	77.36	✓
01 PC	TAIL GATE ENBLEM (LOGO)		na	\$	109.21	✓
01 PC	TAIL GATE ENBLEM (VOXY)		na	\$	182.34	✓
01 PC	TAIL GATE INNER LOCK	581.90	nck	\$	658.75	✓
01 PC	TAIL GATE CATCH LOCK			\$	46.82	X
01 PC	TAIL GATE INNER HANDLE		Bu	\$	63.20	X
02 PC	TAIL GATE INNER STOPPER @ \$40.67		R	\$	81.34	X
02 PC	TAIL GATE NUMBER PLATE LAMP @ \$171.24			\$	342.48	X SVC
02 PC	TAIL LAMP @ \$1295.36	0981-45	cut	\$	2,590.72	✓
02 PC	TAIL LAMP BRACKET @ \$65.31		cut	\$	130.62	✓
01 PC	REAR BUMPER	981.60	Bj	\$	2,449.24	✓
01 PC	REAR BUMPER UNDER COVER		nip	\$	326.45	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30		cut	\$	370.60	at nls
02 PC	REAR BUMPER REFLECTOR @ \$117.14		cut	\$	234.28	✓
02 PC	REAR BUMPER REFLECTOR COVER @ \$140.28		cut	\$	280.56	✓
02 PC	REAR CORNER PANEL @ \$165.30		sr	\$	330.60	X
02 PC	REAR CORNER PANEL BRACKET @ \$144.50		sr	\$	289.00	X
01 PC	REAR END PANEL		Bj	\$	642.20	✓
01 PC	REAR END PANEL TOP GANISH	298.10	Return	\$	365.10	✓
01 PC	REAR SPARE TYRES PANEL		Bu	\$	<del>800.00</del>	✓ 978.10
01 PC	REAR SPARE TYRES BOARD	486.90	cut	\$	786.20	✓
02 PC	REAR INNER PANEL TRIM BOARD @ \$689.53		Bu	\$	1,397.06	✓
01 PC	REAR WEATHERSTRIP	371.85	cut	\$	406.73	✓
01 PC	REAR TAIL GATE CAMERA		fin	\$	650.20	X
01 PC	REAR ANTENNA SENSOR		cut	\$	236.70	✓
01 PC	REAR BUMPER HARNESS		fin	\$	229.87	X
01 PC	REAR WINDSCREEN		na	\$	1,741.50	X
01 PC	REAR WINDSCREEN MOULDING	162	na	\$	320.45	✓
01 PC	REAR EXHAUST		R	\$	645.47	X
03 PC	REAR EXHAUST RUBBER @ \$25.00		fin	\$	75.00	X
		258		\$	24,269.05	

Special Nett

2 PC	PARKING SENSOR @ \$220	nck	\$	880.00	cut
10 PC	REAR TRIM BOARD CLIP @ \$8	na	\$	80.00	✓
01 PC	REAR WINDSCREEN SEALANT		\$	100.00	40JA
01 PC	PHV STICKER	na	\$	25.00	X
06 PC	BUMPER CLIP @ \$8	na	\$	48.00	✓
			\$	1,133.00	

Labour:

1.	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	900	
2.	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00		
3.	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	201	
4.	TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	60h	
5.	TO SUPPLY DIAGNOSTIC & REPROGRAMMING	nn	\$	300.00	X
6.	TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	1201	
		\$	2,950.00		

TOTAL PARTS	\$	24,269.05
TOTAL SPECIAL NETT	\$	1,133.00
TOTAL LABOUR	\$	2,950.00
TOTAL COST OF REPAIR	\$	28,352.05



JD MOTORSPORTS PTE LTD  
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

NOT Authorized  
L1 Rep &  
Permy After Paint  
6 days

DATE : 02/07/2024  
VEHICLE : SNN9491S  
MAKE/MODEL : TOYOTA / VOXY  
CHASSIS NO : ZWR90-0135298  
MILLAGE : 42517KM  
TYRE SIZE : 205/55/R17  
DOA : 26/06/2024

LIST ITEM

01 PC	TAIL GATE	Bu	\$	2,281.24	✓
02 PC	TAIL GATE HINGES @ \$112.74	R	\$	225.48	X
02 PC	TAIL GATE ABSORBER @ \$335.99	Sn	\$	671.98	X
01 PC	TAIL GATE TRIMBOARD	Bu	\$	747.14	✓
01 PC	TAIL GATE OUTER GARNISH	ms CRT	\$	809.06	✓
02 PC	TAIL GATE OUTER LAMP @ \$1127.36	CRT	\$	2,254.72	✓
01 PC	TAIL GATE OUTER SWITCH		\$	365.02	?
01 PC	TAIL GATE EMBLEM (HYBRID)	na	\$	77.36	✓
01 PC	TAIL GATE ENBLEM (LOGO)	na	\$	109.21	✓
01 PC	TAIL GATE ENBLEM (VOXY)	na	\$	182.34	✓
01 PC	TAIL GATE INNER LOCK	nds	\$	658.75	✓
01 PC	TAIL GATE CATCH LOCK		\$ R	46.82	X
01 PC	TAIL GATE INNER HANDLE	Sn	\$	63.20	X
02 PC	TAIL GATE INNER STOPPER @ \$ 40.67	R	\$	81.34	X
02 PC	TAIL GATE NUMBER PLATE LAMP @ \$171.24		\$	342.48	?
02 PC	TAIL LAMP @ \$1295.36	CVT	\$	2,590.72	✓
02 PC	TAIL LAMP BRACKET @ \$65.31		\$	130.62	?
01 PC	REAR BUMPER	Bu	\$	2,449.24	✓
01 PC	REAR BUMPER UNDER COVER	NTP	\$	326.45	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30		\$	370.60	?
02 PC	REAR BUMPER REFLECTOR @ \$117.14	CRT	\$	234.28	✓
02 PC	REAR BUMPER REFLECTOR COVER @ \$140.28	CRT	\$	280.56	✓
02 PC	REAR CORNER PANEL @ \$165.30		\$	330.60	?
02 PC	REAR CORNER PANEL BRACKET @ \$144.50		\$	289.00	?
01 PC	REAR END PANEL	Bu	\$	642.20	✓
01 PC	REAR END PANEL TOP GANISH	Refurn	\$	365.10	✓
01 PC	REAR SPARE TYRES PANEL		\$	854.36	?
01 PC	REAR SPARE TYRES BOARD	CRT	\$	786.20	✓
02 PC	REAR INNER PANEL TRIM BOARD @ \$689.53	Bu	\$	1,397.06	✓
01 PC	REAR WEATHERSTRIP		\$	406.73	?
01 PC	REAR TAIL GATE CAMERA	Sn	\$	650.20	X
01 PC	REAR ANTENNA SENSOR		\$	236.70	?
01 PC	REAR BUMPER HARNESS		\$	229.87	?
01 PC	REAR WINDSCREEN	Bu	\$	1,741.50	X
01 PC	REAR WINDSCREEN MOULDING	na	\$	320.45	✓
01 PC	REAR EXHAUST	R	\$	645.47	X
03 PC	REAR EXHAUST RUBBER @ \$25.00	Sn	\$	75.00	X
			\$	24,269.05	

258

Special Nett

04 PC	PARKING SENSOR @ \$220	nds	\$	880.00	✓
10 PC	REAR TRIM BOARD CLIP @ \$8	na	\$	80.00	✓
01 PC	REAR WINDSCREEN SEALANT		\$	100.00	40JA
01 PC	PHV STICKER	na	\$	25.00	X
06 PC	BUMPER CLIP @ \$8	nds	\$	48.00	✓
			\$	1,133.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	1900l
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	✓
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	20l
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	60l
5. TO SUPPLY DIAGNOTIC & REPROGRAMMING	\$	300.00	?
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	120l
	\$	2,950.00	

TOTAL PARTS  
TOTAL SPECIAL NETT  
TOTAL LABOUR  
TOTAL COST OF REPAIR

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

28352.05

Acknowledged by Repairer  
Signature:  
Date: