

C

1074

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the situation.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources and timeline needed to complete them.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress regularly to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves comparing the actual outcomes against the objectives and goals to determine the effectiveness of the intervention.



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 02/07/2024
VEHICLE : SNN9491S
MAKE/MODEL : TOYOTA / VOXY
CHASSIS NO : ZWR90-0135298
MILLAGE : 42517KM
TYRE SIZE : 205/55/R17
DOA : 26/06/2024

LIST ITEM

01 PC	TAIL GATE	1984.20	Bj	\$	2,281.24	✓
02 PC	TAIL GATE HINGES @ \$112.74		R	\$	225.48	X
02 PC	TAIL GATE ABSORBER @ \$335.99		R	\$	671.98	X
01 PC	TAIL GATE TRIMBOARD		Bu	\$	700.00	✓ 890-60
01 PC	780-10 TAIL GATE OUTER GARNISH		cm	\$	809.06	✓
02 PC	TAIL GATE OUTER LAMP @ \$1127.36	0771-20	cm	\$	2,254.72	✓
01 PC	TAIL GATE OUTER SWITCH			\$	365.02	X
01 PC	TAIL GATE EMBLEM (HYBRID)		nc	\$	77.36	✓
01 PC	TAIL GATE ENBLEM (LOGO)		nc	\$	109.21	✓
01 PC	TAIL GATE ENBLEM (VOXY)		nc	\$	182.34	✓
01 PC	TAIL GATE INNER LOCK	581.90	nc	\$	658.75	✓
01 PC	TAIL GATE CATCH LOCK			\$	46.82	X
01 PC	TAIL GATE INNER HANDLE		Bu	\$	63.20	X
02 PC	TAIL GATE INNER STOPPER @ \$ 40.67		R	\$	81.34	X
02 PC	TAIL GATE NUMBER PLATE LAMP @ \$171.24			\$	342.48	X
02 PC	TAIL LAMP @ \$1295.36	0881-43	cm	\$	2,590.72	✓
02 PC	TAIL LAMP BRACKET @ \$65.31		cm	\$	130.62	✓
01 PC	REAR BUMPER	981.60	Bj	\$	2,449.24	✓
01 PC	REAR BUMPER UNDER COVER		ntp	\$	326.45	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30		cm	\$	370.60	✓ n/s
02 PC	REAR BUMPER REFLECTOR @ \$117.14		cm	\$	234.28	✓
02 PC	REAR BUMPER REFLECTOR COVER @ \$140.28		cm	\$	280.56	✓
02 PC	REAR CORNER PANEL @ \$165.30		sr	\$	330.60	X
02 PC	REAR CORNER PANEL BRACKET @ \$144.50		sr	\$	289.00	X
01 PC	REAR END PANEL		Bj	\$	642.20	✓
01 PC	REAR END PANEL TOP GANISH	298-10	Return	\$	365.10	✓
01 PC	REAR SPARE TYRES PANEL		Bu	\$	786.20	✓ 978-10
01 PC	REAR SPARE TYRES BOARD	486-90	cm	\$	1,397.06	✓
02 PC	REAR INNER PANEL TRIM BOARD @ \$689.53		Bu	\$	406.73	✓
01 PC	REAR WEATHERSTRIP	371-85		\$	650.20	X
01 PC	REAR TAIL GATE CAMERA		cm	\$	236.70	✓
01 PC	REAR ANTENNA SENSOR		Bu	\$	229.87	X
01 PC	REAR BUMPER HARNESS		Bu	\$	1,741.50	X
01 PC	REAR WINDSCREEN		nc	\$	320.45	✓
01 PC	REAR WINDSCREEN MOULDING	162	R	\$	645.47	X
01 PC	REAR EXHAUST		Bu	\$	75.00	X
03 PC	REAR EXHAUST RUBBER @ \$25.00			\$	24,269.05	258

Special Nett

2 PC	PARKING SENSOR @ \$220	nc	\$	880.00	✓
10 PC	REAR TRIM BOARD CLIP @ \$8	nc	\$	80.00	✓
01 PC	REAR WINDSCREEN SEALANT		\$	100.00	✓ 405A
01 PC	PHV STICKER	nc	\$	25.00	X
06 PC	BUMPER CLIP @ \$8	nc	\$	48.00	✓
				\$	1,133.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	900
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	✓
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	201
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	601
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING	nn \$	300.00	X
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	1201
	\$	2,950.00	

TOTAL PARTS	\$	24,269.05
TOTAL SPECIAL NETT	\$	1,133.00
TOTAL LABOUR	\$	2,950.00
TOTAL COST OF REPAIR	\$	28,352.05

Not Authorized
11 Rm @ 10,600/hr
Arriving After Rainy
6 days



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 02/07/2024
VEHICLE : SNN9491S
MAKE/MODEL : TOYOTA / VOXY
CHASSIS NO : ZWR90-0135298
MILLAGE : 42517KM
TYRE SIZE : 205/55/R17
DOA : 26/06/2024

LIST ITEM

01 PC	TAIL GATE	Bj	\$	2,281.24	✓
02 PC	TAIL GATE HINGES @ \$112.74	R	\$	225.48	X
02 PC	TAIL GATE ABSORBER @ \$335.99	Sn	\$	671.98	X
01 PC	TAIL GATE TRIMBOARD	Bu	\$	747.14	✓
01 PC	TAIL GATE OUTER GARNISH	mz cm	\$	809.06	✓
02 PC	TAIL GATE OUTER LAMP @ \$1127.36	cm	\$	2,254.72	✓
01 PC	TAIL GATE OUTER SWITCH		\$	365.02	?
01 PC	TAIL GATE EMBLEM (HYBRID)	na	\$	77.36	✓
01 PC	TAIL GATE ENBLEM (LOGO)	na	\$	109.21	✓
01 PC	TAIL GATE ENBLEM (VOXY)	na	\$	182.34	✓
01 PC	TAIL GATE INNER LOCK	ncl	\$	658.75	✓
01 PC	TAIL GATE CATCH LOCK		\$ R	46.82	X
01 PC	TAIL GATE INNER HANDLE	Sn	\$	63.20	X
02 PC	TAIL GATE INNER STOPPER @ \$ 40.67	R	\$	81.34	X
02 PC	TAIL GATE NUMBER PLATE LAMP @ \$171.24		\$	342.48	?
02 PC	TAIL LAMP @ \$1295.36	cm	\$	2,590.72	✓
02 PC	TAIL LAMP BRACKET @ \$65.31		\$	130.62	?
01 PC	REAR BUMPER	Bj	\$	2,449.24	✓
01 PC	REAR BUMPER UNDER COVER	n tp	\$	326.45	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30		\$	370.60	?
02 PC	REAR BUMPER REFLECTOR @ \$117.14	cm	\$	234.28	✓
02 PC	REAR BUMPER REFLECTOR COVER @ \$140.28	cm	\$	280.56	✓
02 PC	REAR CORNER PANEL @ \$165.30		\$	330.60	?
02 PC	REAR CORNER PANEL BRACKET @ \$144.50		\$	289.00	?
01 PC	REAR END PANEL	Bj	\$	642.20	✓
01 PC	REAR END PANEL TOP GANISH	Refurn	\$	365.10	✓
01 PC	REAR SPARE TYRES PANEL		\$	854.36	?
01 PC	REAR SPARE TYRES BOARD	cm	\$	786.20	✓
02 PC	REAR INNER PANEL TRIM BOARD @ \$689.53	Bu	\$	1,397.06	✓
01 PC	REAR WEATHERSTRIP		\$	406.73	?
01 PC	REAR TAIL GATE CAMERA	Sn	\$	650.20	X
01 PC	REAR ANTENNA SENSOR		\$	236.70	?
01 PC	REAR BUMPER HARNESS		\$	229.87	?
01 PC	REAR WINDSCREEN	Sn	\$	1,741.50	X
01 PC	REAR WINDSCREEN MOULDING	na	\$	320.45	✓
01 PC	REAR EXHAUST	R	\$	645.47	X
03 PC	REAR EXHAUST RUBBER @ \$25.00	Sn	\$	75.00	X
				\$ 24,269.05	258

Special Nett

2 04 PC	PARKING SENSOR @ \$220	ncl	\$	880.00	44
10 PC	REAR TRIM BOARD CLIP @ \$8	na	\$	80.00	✓
01 PC	REAR WINDSCREEN SEALANT		\$	100.00	40JA
01 PC	PHV STICKER	na	\$	25.00	X
06 PC	BUMPER CLIP @ \$8	ncl	\$	48.00	✓
				\$ 1,133.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	1900l
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	✓
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	20l
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	60h
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING	\$	300.00	?
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	120l
		\$	2,950.00

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NOT Authorised
L1 Rep &
Penny After Paint
6 days

28352.05