



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 02/07/2024
VEHICLE : SNN9491S
MAKE/MODEL : TOYOTA / VOXY
CHASSIS NO : ZWR90-0135298
MILLAGE : 42517KM
TYRE SIZE : 205/55/R17
DOA : 26/06/2024

LIST ITEM

01 PC	TAIL GATE	1984.20	Bj	\$	2,281.24	✓
02 PC	TAIL GATE HINGES @ \$112.74		R	\$	225.48	X
02 PC	TAIL GATE ABSORBER @ \$335.99		R	\$	671.98	X
01 PC	TAIL GATE TRIMBOARD		Bu	\$	780.40	✓
01 PC	780.40 TAIL GATE OUTER GARNISH		ms	cm	809.06	✓
02 PC	TAIL GATE OUTER LAMP @ \$1127.36	0771-20	cm	\$	2,254.72	✓
01 PC	TAIL GATE OUTER SWITCH			\$	365.02	X
01 PC	TAIL GATE EMBLEM (HYBRID)		na	\$	77.36	✓
01 PC	TAIL GATE ENBLEM (LOGO)		na	\$	109.21	✓
01 PC	TAIL GATE ENBLEM (VOXY)		na	\$	182.34	✓
01 PC	TAIL GATE INNER LOCK	581.90	nd	\$	658.75	✓
01 PC	TAIL GATE CATCH LOCK			\$R	46.82	X
01 PC	TAIL GATE INNER HANDLE		su	\$	63.20	X
02 PC	TAIL GATE INNER STOPPER @ \$40.67		R	\$	81.34	X
02 PC	TAIL GATE NUMBER PLATE LAMP @ \$171.24			\$	342.48	X
02 PC	TAIL LAMP @ \$1295.36	0881-45	cm	\$	2,590.72	✓
02 PC	TAIL LAMP BRACKET @ \$65.31		cm	\$	130.62	✓
01 PC	REAR BUMPER	981.60	Bj	\$	2,449.24	✓
01 PC	REAR BUMPER UNDER COVER		nip	\$	326.45	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30		cm	\$	370.60	at n/s
02 PC	REAR BUMPER REFLECTOR @ \$117.14		cm	\$	234.28	✓
02 PC	REAR BUMPER REFLECTOR COVER @ \$140.28		cm	\$	280.56	✓
02 PC	REAR CORNER PANEL @ \$165.30		sr	\$	330.60	X
02 PC	REAR CORNER PANEL BRACKET @ \$144.50		sr	\$	289.00	X
01 PC	REAR END PANEL		Bj	\$	642.20	✓
01 PC	REAR END PANEL TOP GANISH	298.10	Return	\$	365.10	✓
01 PC	REAR SPARE TYRES PANEL		Bj	\$	786.20	✓
01 PC	REAR SPARE TYRES BOARD	486.90	cm	\$	1,397.06	✓
02 PC	REAR INNER PANEL TRIM BOARD @ \$689.53		Bu	\$	406.73	✓
01 PC	REAR WEATHERSTRIP	371.85	su	\$	650.20	X
01 PC	REAR TAIL GATE CAMERA		cm	\$	236.70	✓
01 PC	REAR ANTENNA SENSOR		su	\$	229.87	X
01 PC	REAR BUMPER HARNESS		su	\$	1,741.50	X
01 PC	REAR WINDSCREEN		na	\$	320.45	✓
01 PC	REAR WINDSCREEN MOULDING	162	R	\$	645.47	X
01 PC	REAR EXHAUST		su	\$	75.00	X
03 PC	REAR EXHAUST RUBBER @ \$25.00			\$	24,269.05	258

Special Nett

2 PC	PARKING SENSOR @ \$220	nd	\$	880.00	CH
10 PC	REAR TRIM BOARD CLIP @ \$8	na	\$	80.00	✓
01 PC	REAR WINDSCREEN SEALANT		\$	100.00	40JA
01 PC	PHV STICKER	na	\$	25.00	X
06 PC	BUMPER CLIP @ \$8	na	\$	48.00	✓
			\$	1,133.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	900
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	201
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	60h
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	X
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING	\$	300.00	1201
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	
	\$	2,950.00	

TOTAL PARTS	\$	24,269.05
TOTAL SPECIAL NETT	\$	1,133.00
TOTAL LABOUR	\$	2,950.00
TOTAL COST OF REPAIR	\$	28,352.05

Not Authorized
11 Rm 810, 60dp
Penalty After Pains
6 days