

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En	Automobile	
MS	MS FIRST CAPITA	AL INSURANCE LTD	Ref:	CS/FCI24070057/Uvp3	
	16 RAFFLES QUA	Υ	Date:	19/08/2024	
	#42-01 HONG LEC		Code:	FCI2	
_	SINGAPORE 0485				
			ars :- THIRD PARTY CLAI		
	Insured Veh.	SHA 8352G	Veh. Inspected	SNJ 8969J	
	Policy No.	D-24101860MFCT	Coverage	0	
	Claim No.	D24005745MFCT	Excess	\$0.00	
	Assign From	BETTY	Assign Date	02/07/2024	
2. Vehicle Details					
	Make & Model	TOYOTA ALPHARD (A)	C.C	2493	
	Engine No.	2AR2832242	Year of Reg.	02/03/2023	
	Chassis No.	AGH300440626	Colour	BLACK	
	Odometer	81206 KM	Steering	AFFECTED	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM	·		
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	235/50R18	TRIANGLE	6	
	L/H Front Tyre	235/50R18	TRIANGLE	6	
	R/H Rear Tyre	235/50R18	TRIANGLE	6	
	L/H Rear Tyre	235/50R18	TRIANGLE	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	28/06/2024	Inspection Date	02/07/2024	
	Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800			
5a.			Remarks		
B)T⊦	IE INSPECTION WA	ENT TO ACCIDENT REPORT. AS CONDUCTED ON A"WITHOUT P ) YOUR INSTRUCTIONS, WE HAVE		AIRS.	

**Estimate Days of Repair**