







PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 5 of 9)


PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 8 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 9 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SNJ 8969J

