

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email : kyautosg@gmail.com

SNJ8969J - Toyota Alphard

Damaged Area: Front Left Portion

Date: 02/07/2024

D.O.A 28/06/2024

not Authored
mura

2/7/24

P/S

4 days
whip the before part.

Parts / Material :

1	Front bumper	cut/torn	\$	2,690.40	✓
2	Front bumper bracket o/s @ \$206.70	11	\$	413.40	X
3	Front bumper side retainer o/s @ \$203.40	11	\$	406.80	X
4	Front bumper chrome (long) o/s LH & RH @ \$1,290.80	1/5 set o/s	\$	2,581.60	12 C
5	Front bumper chrome bracket LH & RH @ \$325.50	11	\$	651.00	X
6	Front bumper clips set	new	\$	80.00	305/12
7	Headlamp assy LED LH	holder. one	\$	4,980.90	✓
8	Headlamp lower bracket o/s LH & RH @ \$345.60	11	\$	345.60	X
9	Front bumper Chrome short Set LH & RH @ \$1,080.90	11	\$	2,161.80	X
10	Front fender inner shield o/s LHS	11	\$	303.60	X
11	Front fender inner shield clips set	11	\$	80.00	X
12	Front Grille Set With Chrome		\$	3,960.50	?
13	Front bumper cover hole LH & RH @ \$560.50	11	\$	1,121.00	X
14	Front bumper Sensor @ \$435.50 x2	SC	\$	871.00	X
15	Front bumper Lower Grille	11	\$	986.60	X
16	Front Bumper Reinforcement	11	\$	1,680.60	X
17	Front Bumper Foam	11	\$	568.40	X
18	Front Bumper Inner Spoiler Bracket	11	\$	1,360.60	X
19	Towing cover	11	\$	135.60	X
20	Front fender LH	20/304	\$	1,095.40	✓
21	Wheel Rim	cut/needed	\$	1,200.00	✓

Parts: \$ 27,674.80

Less 25%: \$ 6,918.70

Total Parts: \$ 20,756.10

Special Net Items :

Miscellaneous Item

11

\$ 60.00 X

Total S/N Parts: \$ 60.00

Labour :

To Remove & Renew Front Affected Accident Areas	\$	2,000.00	520
To Putty, Spray Paint on Front Affected Accident Areas	\$	1,800.00	800
To conduct computerised wheel alignment	\$	150.00	60
To remove and reinstall wire harness. Check according to damage.	\$	200.00	20
To Conduct & reset ECU diagnostic programme	\$	450.00	?
Total Labour :	\$	4,600.00	

TOTAL PARTS : \$ 20,756.10
TOTAL S/N PARTS: \$ 60.00
TOTAL LABOUR : \$ 4,600.00
TOTAL REPAIR COST : \$ 25,416.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: