

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

SHD4450S

PARTICULAR

QTY

LIST PRICE

ESTIMATE

VEHICLE NO : SLR1590U

MAKE/MODEL : HONDA FREED

ACC DATE : 29.06.2024

UNIT PRICE

AMOUNT

SS

SS

1	1	(SET) REAR WINDSCREEN MOULDING	121.60	121.60
2	1	REAR TAILGATE	1,568.60	1,568.60
3	2	REAR TAILGATE HINGE -RH/LH	58.50	117.00
4	2	REAR TAILGATE DAMPER -RH/LH	175.50	351.00
5	1	REAR TAILGATE RUBBER	189.60	189.60
6	1	REAR TAILGATE LOCK	310.50	310.50
7	1	REAR TAILGATE LOCK CATCH	29.30	29.30
8	1	REAR TAILGATE KEYLESS SMART	191.20	191.20
9	1	REAR TAILGATE KEYLESS BUZZIE	178.80	178.80
10	1	REAR TAILGATE INNER TRIM	561.90	561.90
11	1	REAR TAILGATE EMBLEM 'H'	85.80	85.80
12	1	REAR TAILGATE EMBLEM 'FREED'	86.60	86.60
13	2	REAR TAILLAMP -RH/LH	656.40	1,312.80
14	1	REAR BUMPER	1,210.60	1,210.60
15	1	REAR BUMPER TOW COVER	29.30	29.30
16	2	REAR BUMPER BRACKET -RH/LH	42.50	85.00
17	2	REAR BUMPER SIDE RETAINER -RH/LH	51.20	102.40
18	1	REAR END PANEL	731.30	731.30
19	1	REAR END PANEL GARNISH	241.50	241.50
20	1	FRONT BONNET	741.00	741.00
21	2	FRONT BONNET HINGE -RH/LH	49.50	99.00
22	1	FRONT BONNET RUBBER	69.10	69.10
23	1	FRONT BONNET LOCK	93.80	93.80
24	1	FRONT GRILLE	755.20	755.20
25	1	FRONT GRILLE EMBLEM 'H'	85.80	85.80
26	2	FRONT HEADLAMP -RH/LH	1,599.00	3,198.00
27	2	FRONT HEADLAMP LOWER BRACKET -RH/LH	84.30	168.60
28	1	FRONT BUMPER	918.40	918.40
29	1	FRONT BUMPER TOW COVER	24.80	24.80
30	1	FRONT BUMPER LOWER CENTRE GRILLE	175.50	175.50
31	1	FRONT BUMPER REINFORCMENT	382.20	382.20
32	2	FRONT BUMPER SIDE RETAINER -RH/LH	48.50	97.00
33	1	FRONT FENDER -LH	543.20	543.20
34	1	FRONT SUPPORT PANEL	781.50	781.50
35	1	FRONT SUPPORT PANEL TOP GARNISH	107.20	107.20
36	1	AIR CON CONDENSER	924.40	924.40
37	1	RADIATOR	1,100.80	1,100.80

17,770.30

LESS 20%

3,554.06

14,216.24

not Authorised
has
increased
2/7/24
d/s \$11,000
Admpt to After repair
1 day

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
<u>SPECIAL NETT ITEMS</u>			
1	1 REAR WINDSCREEN SPONGE TAPE <i>nel</i>	20.00	20.00 ✓
2	1 (SET) REAR WINDSCREEN SEALANT <i>nel</i>	80.00	80.00 40
3	1 (SET) REAR BUMPER CLIP <i>nel</i>	45.00	45.00 30
4	1 (SET) REAR BUMPER REVERSE SENSOR <i>SC</i>	280.00	280.00 X
5	1 (SET) FRONT NUMBER PLATE WITH CASING <i>BAO</i>	50.00	50.00 40
6	1 (SET) FRONT BUMPER CLIP <i>nel</i>	50.00	50.00 30
7	1 AIR CON OIL <i>na</i>	45.00	45.00 30
8	1 RADIATOR COOLANT <i>na</i>	25.00	25.00 20
			595.00

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, FRONT SUPPORT PANEL AND REPLACE ACCIDENT PARTS	1,300.00 1000
2	TO SPRAY PAINTING ON ACCIDENT PORTION	2,100.00 1600
3	TO CHECK WIRING	50.00 30
4	TO REMOVE AND REPLACE CONDENSER AND REFILL GAS	100.00 ✓
5	TO REMOVE AND REFIX REAR WINDSCREEN	120.00 ✓
6	TO TRANSFER REAR TAILGATE PARTS	100.00 60
7	TO REMOVE AND REFIX CUSHION AND INNER TRIM	120.00 60
8	TO REMOVE AND REPLACE REVERSE SENSOR <i>REF X</i>	80.00 30
9	TO TUFF KOTE	90.00 ✓
		4,060.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 18,871.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-13302-9
202
1064032
210