

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

TP Sampo
 TX1FAAE1320900015
 Hui Ruy

SNC1642J Nissan Note

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>Dehmd</i>	\$ 1,265.00 <i>689.</i>
2	1 set	Rear bumper reflector <i>Cracked L.H.</i>	\$ 227.00 <i>72</i>
3	1	Rear bumper reinforcement <i>3 new</i>	\$ 493.00 <i>x</i>
4	1	Rear bumper tow cover	\$ 85.00 <i>x</i>
5	1	Rear windscreen glass <i>new</i>	\$ 1,420.00 <i>x</i>
6	1	Rear windscreen glass moulding <i>new</i>	\$ 188.00 <i>✓</i>
7	1	Rear tailgate assy <i>Dented</i>	\$ 1,892.00 <i>1290.</i>
8	1	Rear tailgate lock mechanism <i>Damaged</i>	\$ 245.00 <i>✓</i>
9	1	Rear tailgate inner trim board <i>Cracked</i>	\$ 283.00 <i>✓</i>
10	1	Rear tailgate inner handle <i>Not new</i>	\$ 78.00 <i>x</i>
11	1	Rear tailgate weatherstrip <i>new</i>	\$ 168.00 <i>x</i>
12	2	Rear tailgate hinges <i>Not new</i>	\$ 126.00 <i>x</i>
13	2	Rear tailgate dampers <i>new</i>	\$ 255.00 <i>x</i>
14	1	Rear tailgate inner lamp <i>Not new</i>	\$ 65.00 <i>x</i>
15	1	Rear tailgate note emblem <i>new</i>	\$ 86.00 <i>✓</i>
16	1	Rear tailgate centre logo <i>new</i>	\$ 88.00 <i>✓</i>
17	1	Rear tailgate e power emblem <i>new</i>	\$ 87.00 <i>✓</i>
18	1	Rear right taillamp	\$ 655.00 <i>x</i>
19	1	Rear left taillamp <i>Cracked</i>	\$ 655.00 <i>398</i>
20	1	Rear tailgate right taillamp <i>Cracked</i>	\$ 485.00 <i>275</i>
21	1	Rear tailgate left taillamp <i>Cracked</i>	\$ 485.00 <i>275</i>
22	1	Rear tool kit tray <i>Not new</i>	\$ 185.00 <i>x</i>
23	1	Rear spare tyre top cover <i>Not new</i>	\$ 155.00 <i>x</i>
24	1	Rear end lower panel <i>Dented</i>	\$ 1,152.00 <i>680</i>
25	1	Rear end lower panel top garnish <i>Dehmd</i>	\$ 195.00 <i>✓</i>
26	2	Rear exhaust muffler assy rubber mounting <i>new</i>	\$ 65.00 <i>x</i>
27	1	Rear exhaust muffler assy <i>new</i>	\$ 1,250.00 <i>x</i>
28	1	Rear left fender inner garnish <i>3 new</i>	\$ 315.00 <i>x</i>
29	1	Rear right fender inner garnish	\$ 315.00 <i>x</i>
			\$ 12,963.00
less 10%			\$ 1,296.30
			<u>\$ 11,666.70</u>

4851
 4365.50

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SNC1642J Nissan Note

			Estimated
No	Qty	Parts Description	Parts Price
<u>Special Nett Items</u>			
1	16	Rear bumper clips <i>New</i>	\$ 60.00 <i>30.</i>
2	8	Rear tailgate inner trim board clips <i>New</i>	\$ 50.00 <i>30</i>
3	1	Rear end lower panel sealant <i>New</i>	\$ 140.00 <i>60</i>
4	6	Rear end lower panel top garnish clips <i>New</i>	\$ 40.00 <i>20</i>
5	8	Rear left fender inner garnish clips <i>Green</i>	\$ 40.00 <i>+</i>
6	8	Rear right fender inner garnish clips <i>Green</i>	\$ 40.00 <i>+</i>
7	4	Rear bumper reverse sensor <i>Dund</i>	\$ 1,000.00 <i>200.</i>
8	1	Rear view camera <i>New</i>	\$ 450.00 <i>X</i>
9	1	Rear no plate with garnish <i>Best</i>	\$ 100.00 <i>60</i>
10	1	Rear windscreen glass sealant <i>New</i>	\$ 100.00 <i>60</i>
			\$ 2,020.00

Total parts

\$ 13,686.70

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SNC1642J Nissan Note

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00
2	To putty and spray painting rear portion.	\$ 1,400.00
3	To remove and install rear view camera.	\$ 80.00
4	To remove and install rear tailgate lock mechanism.	\$ 80.00
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00
6	Towing service.	\$ 100.00
7	To remove and install rear exhaust muffler assy.	\$ 120.00
8	To apply anti rust proofing to rear affected area.	\$ 140.00
9	To remove and install rear bumper reverse sensor.	\$ 80.00
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00
Total labour :		\$ 3,690.00

Total parts : \$ 13,686.70

Total labour : \$ 3,690.00

Total repair cost : \$ 17,376.70

S.S.K.

total 6885.90

1/2 : 5.5K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer