

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE SINGAPORE 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: ENG HUEY NI

Date: 26/09/2024

PRELIMINARY ADVICE

| | | | |
|-----------------|----------------|-------------------------|----------------------|
| Vehicle No | GBM 2736E | Accident Date | 29/06/2024 |
| Make | FOTON IBLUE V6 | CLAIM No. | 23/24/24/VC05/029473 |
| Assignment Date | 03/07/2024 | Excess | - |
| Inspection Date | 03/07/2024 | Est. Duration of Repair | 5 |

Inspected At: LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|---------------------------|----|-----------------|
| Workshop Estimate Amount: | \$ | 7,968.90 |
| Revised Estimate Amount: | \$ | 4,320.00 |
| "Check" Items Amount | | \$0.00 |
| Total | \$ | 4,320.00 |

Total Loss Consideration

| | |
|-------------------|-------------|
| Book Value | \$0.00 |
| Market Value | \$90,000.00 |
| COE / PARF Rebate | \$55,512.00 |
| Salvage Value | \$0.00 |
| Margin for Repair | \$34,488.00 |

Remarks

- [] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.