

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN		Ref:	CS/INC24070064/Anh3	
	75 BRAS BASAH F	ROAD SINGAPORE 189557	Date:	28/08/2024	
	INCOME CENTRE	CINONI CINE 100001	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 6474A	Veh. Inspected	SLU 7714A	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1283769-001	Excess	\$0.00	
	Assign From	ASTER QUEK	Assign Date	03/07/2024	
2. Vehicle Details					
	Make & Model	HONDA VEZEL	C.C	1496	
	Engine No.	LEB5927046	Year of Reg.	13/12/2017	
	Chassis No.	RU31227034	Colour	BRONZE	
	Odometer	178975 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60 R16	BLACK ARROW	6	
	L/H Front Tyre	215/60 R16	BLACK ARROW	6	
	R/H Rear Tyre	215/60 R16	BLACK ARROW	6	
	L/H Rear Tyre	215/60 R16	BLACK ARROW	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	27/06/2024	Inspection Date	03/07/2024 (11:20)	
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD	-		
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB			
		SINGAPORE 417921			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					