

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TPWC
Hui Rong

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

TAX INVOICE

Repair Code : CLM16342

Date in : 27/06/2024

Vehicle Num. : SLU7714A

Model : HONDA VEZEL 1.5 HYBRID X

Chassis/Eng# : RU31227034/LEB5927046

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>new</i>	1	250.00	* 250.00
REAR BUMPER REFLECTOR L/R <i>RH Cnld</i>	2	141.10	141.10 282.20
REAR BUMPER SIDE L/R <i>new RH Rehd</i>	2	195.00	195 390.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	* 46.00
REAR END PANEL <i>Dented</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	60.10	+ 60.10
REAR END PANEL BUZZLE SENSOR <i>Cnld</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	98.00	✓ 98.00
REAR FENDER INNER TRIM GARNISH L/R <i>RH Dented</i>	2	295.00	295 590.00
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>Dented</i>	1	485.30	365 485.30
REAR FLOOR PANEL TOP BOARD COVER <i>new</i>	1	430.30	+ 430.30
REAR TAILGATE <i>Dented</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>2 new</i>	1	75.80	✓ 75.80
REAR TAILGATE 'VEZEL' EMBLEM	1	56.20	✓ 56.20
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	27.50	* 27.50
REAR TAILGATE INNER TRIM GARNISH <i>Cnld</i>	1	153.40	✓ 153.40
REAR TAILGATE MECHANISM LOCK <i>Rnd</i>	1	180.00	✓ 180.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

Contact : 87420435 96499449

TAX INVOICE

Repair Code : CLM16342

Date in : 27/06/2024

Vehicle Num. : SLU7714A

Model : HONDA VEZEL 1.5 HYBRID X

Chassis/Eng# : RU31227034/LEB5927046

REAR TAILGATE MECHANISM LOCK STRIKER	1	27.50	27.50
REAR TAILGATE OUTER GARNISH	1	220.00	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	1	25.00	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	2	38.50	77.00
REAR TAILGATE REFLECTOR L/R	2	413.20	826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	18.50	37.00
REAR TAILGATE WEATHER STRIP	1	96.80	96.80
REAR TAILGATE WINDSCREEN INNER SEAL	2	50.00	100.00
REAR TAILGATE WINDSCREEN MOULDING	2	50.00	100.00
REAR TAILLAMP L/R	2	474.60	949.20

Subtotal before discount

7,800.50

Percentage discount 20%

1,560.10

Sub-total 1

6,240.40

REAR BUMPER CLIPS - SET	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR	1	250.00	200 250.00
REAR END PANEL SEALANT	1	80.00	60 80.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	40.00	30 80.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	30 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

Contact : 87420435 96499449

TAX INVOICE

Repair Code : CLM16342

Date in : 27/06/2024

Vehicle Num. : SLU7714A

Model : HONDA VEZEL 1.5 HYBRID X

Chassis/Eng# : RU31227034/LEB5927046

REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>+</i>	40.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	<i>✓</i>	60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	<i>+</i>	60.00
Subtotal before discount				670.00
Percentage discount 0%				0.00
Sub-total 2				670.00
Parts-total				6,910.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

80.00

2,530.00

9,440.40

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
2/8 03/07/24

06 Days

total: 5894.72

C/S: ATK ✓