

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Income Insurance Limited
Income Centre
75 Bras Basah Road Singapore 189557

Attention : Motor Claim Department
Contact : 6788 1777 Fax No. : 6338 1500

Xiao Chen

Estimate : TP24-066

Date : 02/07/2024
Vehicle Num. : GBJ6165S
Make/Model : Toyota Dyna-2019
Chassis/Eng# : JTFAT35Y70K213311/1KD2857156
Accident Date : 26/06/2024
Claim No. :
Reference :
Policy No. : SI23V05728/VCV/R03

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Frt Door RH <i>Repr</i>		1,897.84 <i>+</i>
2.	2	Frt Door Hinge RH (Top/Lower) <i>new</i>	157.20	314.40 <i>+</i>
3.	1	Frt Door Checker RH <i>new</i>		264.50 <i>+</i>
4.	1	Frt Headlamp Assy RH <i>could</i>		1,239.80 <i>-</i>
5.	1	Frt Bumper Assy <i>Dishend</i>		874.51 <i>645</i>
6.	1	Frt Bumper Support <i>3 new</i>		217.50 <i>+</i>
7.	1	Frt Bumper Bracket <i>new</i>		431.60 <i>+</i>
8.	1	Frt Foglamp Cover RH <i>new</i>		125.90 <i>+</i>
9.	1	Frt Corner Panel RH <i>Repr</i>		336.80 <i>+</i>
10.	1	Frt Grille Assy <i>new</i>		695.20 <i>+</i>
List Total S\$:				6,398.05
25.00% Discount S\$:				1,599.51
				4,798.54
SPECIAL NETT ITEMS :				
1.	1	Frt Bumper Clips <i>new</i>		30.00 <i>-</i>
2.	1	Frt door company sticker <i>new</i>		35.00 <i>-</i>
Special Nett Total S\$:				65.00
LABOUR :				
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				1,200.00 <i>4w</i>
To remove, rearrange electrical wirings, check lighting				80.00 <i>30</i>
To putty and respray painting on frt bumper,				1,000.00 <i>4w</i>

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

Income Insurance Limited
 Income Centre
 75 Bras Basah Road Singapore 189557

Attention : Motor Claim Department
 Contact : 6788 1777 Fax No. : 6338 1500

Estimate : TP24-066

Date : 02/07/2024
 Vehicle Num. : GBJ61655
 Make/Model : Toyota Dyna-2019
 Chassis/Eng# : JTFAT35Y70K213311/1KD2857156
 Accident Date : 26/06/2024
 Claim No. :
 Reference :
 Policy No. : SI23V05728/VCV/R03

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

frt corner panel RH, frt door RH, frt panel
 and frt grille assy.

Labour Total S\$:

2,280.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Stamp:

Adnan L
 2/s 03/07/24.
 030 days

total: 2308.60
 2/s : 1850 ✓

Total S\$: 7,143.54
 =====


 SUCCESS UNITED PTE LTD