

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24070068/AMA3Q2
Date: 19/11/2024

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220131522
Claimant Vehicle No : SMU5331Y Insured Vehicle No : SNG8033A
Date of Loss: 12/06/2024 Nature of Claim: TP Claim No: 0528903773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMU5331Y
Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE SALOON AUTO (A) Engine No: 28291480211004
Reg. Date: 09/07/2020 (Man. Year: 2019) Chassis No: WDD1771872J119679
Colour: Blue Odometer: 80808 km
Engine Capacity: 1332 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/35 R19 Rear Tyre Size: 225/35 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,804.00	13,381.70	13,422.30	50.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,930.00	2,240.00	6,690.00	74.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,734.00	15,621.70	20,112.30	56.28
Approved Total (Overridden) (S\$)		12,500.00		
(S\$)	35,734.00	12,500.00	23,234.00	65.02
+ GST 9.00/9.00% (S\$)	3,216.06	1,125.00	2,091.06	65.02
Nett Amount (S\$)	38,950.06	13,625.00	25,325.06	65.02
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		14,552.25		
Global Sum Settlement (S\$)		14,500.00		

INSPECTION

Date of Assignment: 27/06/2024
Date Inspected: 27/06/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE SKIRT LH	Not Necessary	866.00 FL	*- FL
2	1		*REAR DOOR LH	Dented	3,112.00 FL	*2,588.00 FL
3	1		*REAR DOOR FRAME WEATHERSTRIP LH	Not Necessary	315.00 FL	*- FL
4	1		*REAR DOOR HINGE LH (TOP)	Not Necessary	208.00 FL	*- FL
5	1		*REAR DOOR HINGE LH (BOTTOM)	Not Necessary	340.00 FL	*- FL
6	1		*REAR DOOR INNER LOCK LH	Damaged	1,122.00 FL	*569.00 FL
7	1		*REAR DOOR INNER TRIM LH	Cracked	2,412.00 FL	*1,264.00 FL
8	1		*REAR DOOR LOCK CATCHER LH	Not Necessary	58.00 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP LH	Necessary	345.00 FL	*345.00 FL
10	1		*REAR DOOR OUTER STEP LH	Not Necessary	208.00 FL	*- FL
11	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	565.00 FL	*- FL
12	1		*REAR DOOR REGULATOR LH	Damaged	1,116.00 FL	*464.00 FL
13	1		*REAR DOOR GLASS CHANNEL LH	Not Necessary	315.00 FL	*- FL
14	1		*REAR FENDER LH	Dented	3,360.00 FL	*2,623.00 FL
15	1		*REAR FENDER INNER COWLING LH	Torn	214.00 FL	*214.00 FL
16	1		*REAR WINDSCREEN GLASS C/W MOULDING	Necessary	1,908.00 FL	*220.00 FL
17	1		*REAR WHEEL RIM LH	Cut	1,310.00 FL	*1,310.00 FL
18	1		*REAR UPPER ARM LH	Bent	571.00 FL	*571.00 FL
19	1		*REAR LOWER ARM LH	Bent	835.00 FL	*712.00 FL
20	1		*REAR KNUCKLE ARM LH	Damaged	1,509.00 FL	*1,315.00 FL
21	1		*REAR LINKAGE LH	Not Necessary	105.00 FL	*- FL
22	1		*REAR CONTROL ARM LH	Bent	219.00 FL	*219.00 FL
23	1		*REAR ABS SENSOR LH	Not Necessary	112.00 FL	*- FL
24	1		*REAR SHOCK ABSORBER LH	Not Necessary	636.00 FL	*- FL
25	1		*REAR WHEEL HUB WITH BEARING LH	Damaged	599.00 FL	*599.00 FL
26	1		*SIDE SKIRT (SPECAIL TYPE)	Deformed	800.00 FS	*480.00 FS
27	1		*SIDE SKIRT CLIP LH	Necessary	60.00 FS	*30.00 FS
28	1		*SET REAR DOOR FRAME STEP GARNISH CLIP LH	Not Necessary	30.00 FS	*- FS
29	1		*SET REAR DOOR INNER TRIM CLIP LH	Necessary	50.00 FS	*30.00 FS
30	1		*REAR DOOR BOTTOM RUBBER CLIP LH	Not Necessary	50.00 FS	*- FS
31	1		*REAR DOOR WRAPPING (SPECAIL TYPE)	Necessary	800.00 FS	*400.00 FS
32	1		*REAR DOOR STICKER (AMG) (SPECAIL TYPE)	Necessary	350.00 FS	*180.00 FS
33	1		*REAR FENDER SEALANT LH	Necessary	80.00 FS	*60.00 FS
34	1		*REAR FENDER COWLING CLIP (SET)LH	Necessary	80.00 FS	*30.00 FS
35	1		*REAR FENDER INNER TRIM CLIPS (SET)LH	Not Necessary	80.00 FS	*- FS
36	1		*REAR FENDER WRAPPING (SPECAIL TYPE)	Necessary	1,200.00 FS	*400.00 FS
37	1		*REAR WINDSCREEN REPAIR KIT	Necessary	350.00 FS	*60.00 FS
38	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
39	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Not Necessary	150.00 FS	*- FS
41	1		*REAR BUMPER WRAPPING (SPECAIL TYPE)	Not Necessary	1,000.00 FS	*- FS
42	1		*REAR WHEEL TYRE LH	Not Necessary	850.00 FS	*- FS
43	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
44	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,040.00	14,683.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,236.00	1,301.30
Total Parts (\$\$)	26,804.00	13,381.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING MREMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	250.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	650.00	40.00
7	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	1,200.00	250.00
9	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
10	REMOVE & REFIX FUEL TANK	New	150.00	0.00
11	TRANFER REAR DOOR MECHANISM RH	New	80.00	40.00
12	REMOVE & REINSTALL REAR WINDOW GLASS RH	New	60.00	40.00
13	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
14	REMOVE & REFIX REAR SENSOR	New	250.00	0.00
15	FOUR WHEEL ALIGNMENT	New	120.00	80.00
16	RESET AIR BAG LIGHT	New	1,200.00	0.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	850.00	200.00
Gross Labour Cost (\$\$)			8,930.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >