

JL Perfect Autowork Pte Ltd
Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 27.06.2024

TO : **AIG MOTOR CLAIMS DEPTS**
VEHICLE NO : **SMU5331Y**
MODEL : **MERCEDES A200**
DATE OF ACCIDENT : 12.06.2024
TIME OF ACCIDENT : 19:25 HOURS

WDD1771872J119679

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT LH <i>Rebuilt New</i>	1	\$ 866.00	\$ 866.00
2	REAR DOOR LH <i>Devised</i>	1	\$ 3,112.00	\$ 3,112.00
3	REAR DOOR FRAME WEATHERSTRIP LH <i>new</i>	1	\$ 315.00	\$ 315.00
4	REAR DOOR HINGE LH (TOP) <i>new</i>	1	\$ 208.00	\$ 208.00
5	REAR DOOR HINGE LH (BOTTOM) <i>new</i>	1	\$ 340.00	\$ 340.00
6	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 1,122.00	\$ 1,122.00
7	REAR DOOR INNER TRIM LH <i>new</i>	1	\$ 2,412.00	\$ 2,412.00
8	REAR DOOR LOCK CATCHER LH <i>new</i>	1	\$ 58.00	\$ 58.00
9	REAR DOOR WEATHER STRIP LH <i>new</i>	1	\$ 345.00	\$ 345.00
10	REAR DOOR OUTER STRIP LH <i>new</i>	1	\$ 208.00	\$ 208.00
11	REAR DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 565.00	\$ 565.00
12	REAR DOOR REGULATOR LH <i>new</i>	1	\$ 1,116.00	\$ 1,116.00
13	REAR DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 315.00	\$ 315.00
14	REAR FENDER LH <i>Revised Devised</i>	1	\$ 3,360.00	\$ 3,360.00
15	REAR FENDER INNER COWLING LH <i>new</i>	1	\$ 214.00	\$ 214.00
16	REAR WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 1,908.00	\$ 1,908.00
17	REAR WHEEL RIM LH <i>new</i>	1	\$ 1,310.00	\$ 1,310.00
18	REAR UPPER ARM LH <i>new</i>	1	\$ 571.00	\$ 571.00
19	REAR LOWER ARM LH <i>new</i>	1	\$ 835.00	\$ 835.00
20	REAR KUNCKLE ARM LH <i>new</i>	1	\$ 1,509.00	\$ 1,509.00

+ 2588
+ 569
+ 1264
+ 464
+ 2623
+ 220
+ 12
1315

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMU5331Y**
 MODEL : **MERCEDES A200**
 DATE OF ACCIDENT : 12.06.2024
 TIME OF ACCIDENT : 19:25 HOURS

21	REAR LINKAGE LH <i>new</i>	1	\$	105.00	\$	105.00	<i>+</i>
22	REAR CONTROL ARM LH <i>new</i>	1	\$	219.00	\$	219.00	<i>+</i>
23	REAR ABS SENSOR LH <i>new</i>	1	\$	112.00	\$	112.00	<i>+</i>
24	REAR SHOCK ABSORBER LH <i>new</i>	1	\$	636.00	\$	636.00	<i>+</i>
25	REAR WHEEL HUB WITH BEARING LH <i>new</i>	1	\$	599.00	\$	599.00	<i>+</i>

13013

11711.70

TOTAL PRICE \$ 22,360.00
 LESS 10% \$ 2,236.00
SUB TOTAL PRICE \$ 20,124.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTALS/NETT	
1	SIDE SKIRT (SPECAIL TYPE) <i>new</i>	1	\$ 800.00	\$ 800.00	<i>480</i>
2	SIDE SKIRT CLIP LH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
3	REAR DOOR FRAME STEP GARNISH CLIP LH (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	REAR DOOR INNER TRIM CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
5	REAR DOOR BOTTOM RUBBER CLIP LH <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	REAR DOOR WRAPPING (SPECAIL TYPE) <i>new</i>	1	\$ 800.00	\$ 800.00	<i>400 400</i>
7	REAR DOOR STICKER (AMG)(SPECIL TYPE) <i>new</i>	1	\$ 350.00	\$ 350.00	<i>180</i>
8	REAR FENDER SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>60</i>
9	REAR FENDER COWLING CLIP (SET) LH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
10	REAR FENDER INNER TRIM CLIPS (SET)LH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
11	REAR FENDER WRAPPING (SPECAIL TYPE) <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	<i>400</i>
12	REAR WINDSCREEN REPAIR KIT <i>new</i>	1	\$ 350.00	\$ 350.00	<i>60</i>
13	REAR WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00	<i>+</i>
14	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
15	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
16	REAR BUMPER WRAPPING (SPECAIL TYPE) <i>new</i>	1	\$ 1,000.00	\$ 1,000.00	<i>+</i>
17	REAR WHEEL TYRE LH <i>new</i>	1	\$ 850.00	\$ 850.00	<i>+</i>
18	WHEEL CAP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
19	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

TOTAL \$ 6,680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1670

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMU5331Y**
 MODEL : **MERCEDES A200**
 DATE OF ACCIDENT : 12.06.2024
 TIME OF ACCIDENT : 19:25 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	550 800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	400 600
3	TUFF COAT	\$ 250.00	40
4	WIRING CHECK	\$ 250.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
6	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 650.00	40
7	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
8	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 1,200.00	7 250
9	TO PRESS REAR WHEEL BEARING	\$ 80.00	X
10	REMOVE & REFIX FUEL TANK	\$ 150.00	X
11	TRANSFER REAR DOOR MECHANISM RH	\$ 80.00	40
12	REMOVE & REINSTALL REAR WINDOW GLASS RH	\$ 60.00	40
13	REMOVE & REFIX REAR WINDSCREEN	\$ 150.00	X 120
14	REMOVE & REFIX REAR SENSOR	\$ 250.00	X
15	FOUR WHEEL ALIGNMENT	\$ 120.00	80

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SMU5331Y
MODEL : MERCEDES A200
DATE OF ACCIDENT : 12.06.2024
TIME OF ACCIDENT : 19:25 HOURS

16	RESET AIR BAG LIGHT	\$ 1,200.00	x
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 850.00	* 200

2240

TOTAL \$ 8,930.00

TOTAL PARTS COST : \$ 26,804.00
TOTAL LABOUR COST : \$ 8,930.00
TOTAL REPAIR COST : \$ 35,734.00

Adnan L
2/s 27/06/24.
[Signature]
28 hrs

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Total 15821.70
L/S: 12.5K

12.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: