



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|-------------------------------------|-------|-----------------------|
| MS GREAT AMERICAN INSURANCE COMPANY | Ref: | CS/GAI24070069/Kvp3e2 |
| 3 TEMASEK AVENUE | Date: | 03/07/2024 |
| #16-01 CENTENNIAL TOWER | Code: | GAI |
| SINGAPORE 039190 | | |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------------|----------------|------------|
| Insured Veh. | SMX 1139Y | Veh. Inspected | SMW 5469Z |
| Policy No. | - | Coverage | 0 |
| Claim No. | CLMOMVP000001562 | Excess | \$0.00 |
| Assign From | - | Assign Date | 03/07/2024 |

2. Vehicle Details

| | | | |
|-----------------|-------------------|--------------|----------------|
| Make & Model | MAZDA 6 (A) | C.C | 1998 |
| Engine No. | PE21302408 | Year of Reg. | 31/05/2019 |
| Chassis No. | JM6GL1072K0322559 | Colour | METALLIC BLACK |
| Odometer | 103177 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|-------------|--------------|
| R/H Front Tyre | 225/50R18 | BRIDGESTONE | 4 |
| L/H Front Tyre | 225/50R18 | BRIDGESTONE | 4 |
| R/H Rear Tyre | 225/50R18 | BRIDGESTONE | 2 |
| L/H Rear Tyre | 225/50R18 | BRIDGESTONE | 2 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 29/06/2024 | Inspection Date | 04/07/2024 |
| Survey held at | BLK 10 SIN MING IND EST SECTOR C #01-08 - CARWORKZ | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days