

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Tel : 6389 - 6111
Fax : 6224 - 7478 / 7175

Quotation

DATE : 04.07.2024
VEH NO : SLZ5330K
MODEL : Mazda 3
D O A : 22.06.2024
YR REF : SNE8074S

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

Veron.

RE : ESTIMATE FOR ACCIDENT REPAIR SLZ5330K (MAZDA 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>xhr</i>	2	142.20 <i>+</i>
2	Rear Bumper <i>debride</i>	1	1,028.60 <i>✓</i>
3	Rear Bumper Side Holder - LH & RH <i>xhr</i>	2	72.20 <i>+</i>
4	Rear Bumper Reflector - LH & RH <i>xhr</i>	2	115.00 <i>+</i>
5	Rear Bumper Tow Cover - LH & RH <i>xhr</i>	2	110.00 <i>+</i>
6	Rear Bumper Reinforcement <i>debride</i>	1	498.40 <i>✓</i>
7	Rear End Panel <i>1527</i>	1	586.20 <i>+</i>
8	Rear End Panel Top Garnish	1	214.20 <i>+</i>
9	Tail Lamp - LH & RH <i>1221-60</i>	2	1,070.00 <i>+</i>
10	Boot Lid <i>xhr</i>	1	1,066.20 <i>+</i>
11	Boot Lid Lock <i>xhr</i>	1	225.20 <i>+</i>
12	Boot Lid Weatherstripe	1	135.60 <i>+</i>
13	Mazda Logo	1	56.90 <i>+</i>
14	Mazda 3 Wording	1	59.40 <i>+</i>
15	Skyactiv Emblem	1	63.60 <i>+</i>
16	Rear Fender Inner Trim Cover - LH & RH <i>xhr</i>	2	570.40 <i>+</i>
			\$ 6,014.10
Less 20%			
			\$ (1,202.82)
			\$ 4,811.28

S/NETT ITEMS

1	Front <i>Rear</i> Bumper Clips <i>xhr</i>	1 set	50.00 <i>30</i>
2	Reverse Sensor <i>debride</i>	1	200.00 <i>200</i>
3	Rear End Panel Top Garnish Clips <i>xhr</i>	1 set	20.00 <i>X</i>
4	Rear End Panel Sealant <i>xhr</i>	1 set	60.00 <i>X</i>
			410.00

RE : ESTIMATE FOR ACCIDENT REPAIR SLZ5330K (MAZDA 3)

Total parts

\$ 5,221.28

LABOUR CHARGE

1	To knocking out front rear portion & renew above parts	\$	1,200.00 200
2	To putty & spray up paint works	\$	1,200.00 300
3	To check wiring	\$	50.00 30
4	To apply tuff coat	\$	150.00 +
5	To remove upholstery	\$	150.00 +
6	To transfer bootlid fittings	\$	150.00 +
7	To remove reverse sensor	\$	100.00 50
8	To remove rear camera	\$	100.00 +

Total Labour

\$ 3,100.00

Grand Total

\$ 8,321.28

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 2031 60
4/5: 1-6 K
02 hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: