



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorised

8 July 2024

REG NO.: SFX 3339 G
MAKE/MODEL: BMW 420i

3/7/24
1/5 @ 9600/
telephoned After repair

6 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
<u>LIST ITEMS</u>		
1	Rear boot lid 20/3at	\$ 1,680.00 ✓
2	Rear boot hinges 11	\$ 280.00 X
2	Rear boot lamps 11	\$ 900.00 X
1	Rear boot lock - lower 11	\$ 280.00 X
1	Rear boot lock catch - upper 11	\$ 55.80 X
1	Rear boot logo 11	\$ 120.00 ✓
1	Rear boot "440i" emblem 11	\$ 62.60 ✓
1	Rear taillamp 0/5 11	\$ 825 1,240.00 ✓
2	Rear taillamp side garnishes 11	\$ 179.80 X
1	Rear end panel 5ady 20	\$ 792.30 ✓
1	Rear end panel inner garnish 11	\$ 490.00 X
2	Rear bumper brackets 3at	\$ 60x2 = 120 390.00 ✓
1	Rear bumper clip (1 set) 11	\$ 50.00 ✓
1	Rear bumper inner frame garnish 11	\$ 190.00 ✓
4	Rear bumper PDC sensors 11	\$ 225x2 = 450 1,420.00 2pc ✓
2	Rear bumper reflectors 11	\$ 66x2 = 132 390.00 ✓
1	Rear bumper reinforcement 11	\$ 499.00 550.00 ✓
2	Rear bumper side retainers 11	\$ 240.00 X
1	Rear bumper tow hook cover 11	\$ 92.00 X
1	Control unit for rear function module 11	\$ 565.20 X
1	Control module for park assistant kit 11	\$ 360.00 508.90 ✓
1	Rear bumper top retainer 11	\$ 180.00 342.10 ✓
1	Rear exhaust silencer 11	\$ 1,947.40 ✓
2	Rear exhaust mountings 11	\$ 96.00 X
2	Rear exhaust chrome tail pipes 0/5 7m	\$ 120 277.40 1pc ✓
1	Rear exhaust heat shield 11	\$ 225 794.00 ✓
		\$ 13,933.50
Less 5%		\$ 696.68
		\$ 13,236.83

SPECIAL NETT ITEMS

- 1 Rear bumper -M Sport
1 Rear bumper lower spoiler
1 *Set* Rear wrap sticker
1 Rear number plate with holder

\$	<i>DIS</i>	2,800.00	<i>1600</i>
\$	<i>DIS</i>	850.00	<i>750</i>
\$	<i>new</i>	450.00	<i>✓</i>
\$	<i>Damage</i>	80.00	<i>40</i>
\$		<u>4,180.00</u>	

S/N**LABOUR CHARGES**

- 1 To remove, replaced damaged lamps and check up rear wiring.
2 To remove and refit inner garnishes.
3 To remove and refit rear reverse sensor.
4 To transfer boot lid mechanism and wiring assembly.
5 To remove, refit and replace exhaust silencer and mountings.
6 To apply undercoating.
7 Panel beating.
8 To re-spray painting on the affected areas.

\$	80.00	<i>20</i>
\$	180.00	<i>80</i>
\$	180.00	<i>30</i>
\$	80.00	<i>60</i>
\$	150.00	<i>80</i>
\$	200.00	<i>50</i>
\$	2,200.00	<i>800</i>
\$	<u>2,000.00</u>	<i>700</i>
\$	5,070.00	

GRAND TOTAL :**\$ 22,486.83**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-77533
52
7364.64
2840
1820
12025.64
202
9620.