

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24070073/ENP3E2
Date: 15/07/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00601
Claimant Vehicle No :	SHD8622L	Insured Vehicle No :	SNN5935E
Date of Loss:	02/07/2024	Nature of Claim:	TP
		Claim No:	M2403683

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD8622L		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU112374
Reg. Date:	04/12/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU115263
Colour:	Yellow	Odometer:	579482 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,257.32	844.44	412.88	32.84
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,150.00	1,240.00	910.00	42.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,419.32	2,096.44	1,322.88	38.69
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	3,419.32	1,700.00	1,719.32	50.28
+ GST 9.00/9.00% (\$\$)	307.74	153.00	154.74	50.28
Nett Amount (\$\$)	3,727.06	1,853.00	1,874.06	50.28

INSPECTION

Date of Assignment:	03/07/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/07/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2024)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD8622L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Repair	481.10 FL	*- FL
2	1		*FRT BUMPER SIDE BRACKET RH	Not Necessary	35.00 FL	*- FL
3	1		*FRT FENDER RH	Dented	588.80 FL	*588.80 FL
4	1		*FRT FENDER EMBLEM RH	Necessary	26.60 FL	*26.60 FL
5	1		*FRT WHEEL RIM CAP	Broken	346.40 FL	*346.40 FL
6	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 F	*75.00 F
					Sub Total (\$\$)	1,552.90 1,036.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	295.58 192.36
					Total Parts (\$\$)	1,257.32 844.44

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	380.00
2	SPARYPAINT CHARGES	New	900.00	840.00
3	TUFF KOTE	New	50.00	20.00
Gross Labour Cost (\$)			2,150.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >