

INFINITY AUTO 57 PTE LTD

Business Reg. No: 53178727C

(Repair & Insurance Claim)

Blk 3020A Ubi Road 1, #01-33, Singapore 48714

H/P : 81862100

Fax: 67431964

JT FIAT02P900245844

Vehicle number : **GBH8715C**
Date of Accident : **29/9/2024**
Accident along : **CHAI CHEE ROAD**

Vehicle make : **TOYOTA**
Vehicle model: **HIACE**

Parts

- 1 Front side mirror *cut*
- 2 Sliding door *distorted*
- 3 Sliding door weatherstrip *new*
- 4 Sliding door inner trim board *from*
- 5 Sliding door lock *new*
- 6 Sliding door outer handle *new*
- 7 Sliding door centre roller *Best*
- 8 Sliding door lower roller *as is*
- 9 Taillamp *cut*
- 10 Taillamp lower garnish *Repair*
- 11 Taillamp lower retainer *new*
- 12 Rear bumper *Repair*
- 13 Rear bumper side retainer LH *from*
- 14 Rear bumper side retainer RH *from*
- 15 Rear fender *Repair*
- 16 Rear fender inner trim board *new*
- 17 Rear end panel *new*
- 18 Rocker panel *new*

450.20 ✓

~~2,185.65~~ ✓ 1817

348.50 ✗

~~457.20~~ ✓ 165

282.50 ✓

198.50 +

148.30 ✓

187.40 +

355.20 ✓

257.40 +

53.70 +

673.10 +

78.20 +

78.20 +

1,828.90 ✗

457.20 +

Repair +

Repair ✗

Total parts

25%

8,040.15

2,010.04

6,030.11

3568.70

2676.52

- 1 Sliding door inner trim board clip *new*
- 2 Rear bumper clips *new*
- 3 Rear fender inner trim board clips *new*
- 4 Rear rim *new*
- 5 Rear hup cap *cut*
- 6 Rear fender insulator pad *new*

50.00 30

50.00 +

50.00

400.00 + 150 ✗

150.00 120

300.00 +

150

Total parts

1,000.00

Labour

- 1 Labour
- 2 Spray painting
- 3 Rewire
- 4 Antirust
- 5 Wheel alignment
- 6 Upholster
- 7 Transfer sliding door parts
- 8 R&R reverse sensor
- 9 R&R rear rim for balancing
- 10 R&R rear tyre
- 11 To redo sealant on gap
- 12 To conduct water leakage test

~~1,200.00~~ 500
~~1,200.00~~ 600
~~50.00~~ 30
~~100.00~~ 40
~~100.00~~ 80
~~300.00~~ 60
~~200.00~~ 60
50.00 +
50.00 +
50.00 +
100.00 +
100.00 +

1370

Total labour

3,500.00

Total repair cost

10,530.11

08 working days repair

Adrian Lj

2/s 03/07/24

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4196.52

2/s: 3.3k ✓