

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0463/2024/EQ
DATE : 11-Jun-24
WIP : 19110

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/6/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Steve,

3 Days - OK - Allan Boo

12-Jul-24

OWNER'S NAME : MR MATHUR ANURAG CHANDRA
ADDRESS : WATERSIDE, BLOCK 3
#04-04
SINGAPORE 436881
TELEPHONE : HP +65 98247729
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800075916-06
VEHICLE NO : **SMC 1230 B**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 26/6/2018
ENGINE NO : CZD 870549
CHASSIS NO : WAUZZZ8U7JR070338
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jun-24
PLACE OF ACCIDENT : ENTRANCE OF FORT ROAD FROM ECP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 1230 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER.	\$	1,200.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		: \$	3,852.00	\$ 1,702.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 1230 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,544.00	\$	2,035.20
2	FRONT BUMPER FIXING PARTS	1	\$ 122.00		
3	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 384.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 272.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 221.00		
6	FRONT BUMPER SPOILER	1	\$ 479.00		
7	RADIATOR GRILLE	1	\$ 1,421.00	\$	1,136.80
8	RADIATOR GRILLE STRIKER PLATE	1	\$ 163.00	\$	130.40
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 129.00		
10	FRONT BUMPER SIDE REINFORCEMENT BEAM	1	\$ 1,116.00		
11	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 82.00		
12	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 30.00		
13	FRONT WHEEL COVER - LH / RH	2	\$ 612.00	\$	488.80
14	HEADLIGHT - RH	1	\$ 9,325.00		
15	HEADLIGHT RETAINING PLATE - RH	1	\$ 109.00		
16	LIFT CYLINDER - RH	1	\$ 167.00		
17	LIFT CYLINDER HOSE	1	\$ 233.00		
18	HEADLIGHT MOUNTING - RH	1	\$ 147.00		
19	HEADLIGHT SUPPORT - RH	1	\$ 32.00		
20	FRONT NUMBER PLATE	S/N	\$ 60.00		
21	SUNDRIES		\$ 500.00		
TOTAL SPARE PARTS			\$ 18,148.00	\$	3,791.20
TOTAL LABOUR CHARGES			\$ 3,852.00	\$	1,702.00
GRAND TOTAL			\$ 22,000.00	\$	5,493.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT