

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Toh, Yuslinda

Date: 25 Jun 2024

**Preliminary Advice**

Vehicle No	: SMX3836E	Accident Date	: 20/06/2024
Make	: AUDI A7 SPORTBACK	Policy No.	: 2070161277
Assignment Date	: 21/06/2024	Excess	: S\$600.00
Date of Inspection	: 24/06/2024	Est. Duration of Repair	: 6
Inspection At	: 24 BENOI SECTOR		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,170.00
Revised Amount	:S\$	26,757.00
Check Items (Estimated)	:S\$	2,513.00
Total	:S\$	29,270.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	229,000.00
COE / PARF Rebate	:S\$	78,590.00
Salvage Value	:S\$	
Margin for Repair	:S\$	150,410.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Kindly advise the Paint coating with policy insured ?  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.