

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 02 / 07 / 2024

ESTIMATE	COSTS	OF	REPAIR
----------	-------	----	--------

M/s Handicaps Welfare Association

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*Not withstanding
C/Sing @ 6200/-
Running After Rain
Today*

Dear Sir / Madam ,

Vehicle no. : PC 1439 G - Toyota Hiace Highroof Auto 14 Seater

Accident date : 01 / 07 / 2024

Quantity		Descriptions	Amount (S\$)
1	1 pc	tail gate	\$ <i>RM</i> 3,052.40 ✓
2	1 pc	tail gate weather strip	\$ <i>RM</i> 387.50 X
3	1 pc	tail gate windscreen glass molding	\$ <i>NSP</i> 109.00 X
4	1 pc	tail gate inner lock	\$ <i>R</i> 262.30 X
5	1 pc	tail gate 'Toyota' logo	\$ <i>RM</i> 71.60 ✓
6	1 pc	tail gate 'Hiace' sticker	\$ <i>RM</i> 71.60 ✓
7	1 pc	n/s tail lamp	\$ <i>GR</i> 379.47 ✓
8	2 pcs	n/s tail lamp lower garnish	\$ <i>RM</i> 158.40 ✓
9	2 pcs	n/s tail lamp lower garnish retainer	\$ <i>CM</i> 35.80 ✓
10	1 pc	rear bumper fascia	\$ <i>CM</i> 519.87 ✓
11	1 pc	n/s rear bumper air duct	\$ <i>Del</i> 40.70 ✓
12	1 pc	n/s rear bumper side retainer	\$ <i>CM</i> 22.20 ✓
13	2 pcs	rear bumper bracket 1 @ 24.60	\$ <i>R</i> 49.20 X
14	1 pc	n/s rear mudflap	\$ <i>RM</i> 173.20 X
15	1 pc	n/s rear fender	\$ <i>Bvel wrap</i> 1,524.01 ✓
16	1 pc	n/s rear fender inner garnish	\$ <i>RM</i> 958.60 X
17	1 pc	n/s rear fender outer garnish	\$ <i>RM</i> 286.00 X
18	1 pc	rear end panel	\$ <i>R</i> 410.30 X
			\$ 8,512.15
Less 25%			\$ 2,128.04
Balance C/FD			\$ 6,384.11

Co. and GST Reg. No. : 200820153N

\$	6,384.11
----	----------

\$	Mr	50.00	sn	155n
\$	Mr	50.00	sn	155n
Mr \$		1,200.00	sn	705n
\$	nn	250.00	sn	2
\$	Mr	120.00	sn	405n
\$	Mr	120.00	sn	305n
\$	Mr	100.00	sn	405n
\$	Mr	100.00	sn	305n
\$	na	100.00	sn	x
\$	na	100.00	sn	x
\$	nd	450.00	sn	2005n
\$		9,024.11		

Labour charges	\$	2,800.00	0001
To putty and spray painting	\$	1,800.00	10001
Re-seal anti rust	\$	250.00	601
To check, replace, repair wiring	\$	150.00	201
To remove and refix reverse sensor	\$	120.00	501
Remove & refix rear windscreen glass	\$	160.00	1201
Remove & refix rear rear reverse camera	\$	160.00	501
Remove & refix n/s rear fender quarter glass	\$	200.00	1001
Remove & refix n/s rear central glass	\$	200.00	NA
Remove & refix rear tailgate glass	\$	200.00	NA
Remove and refix tail gate	\$	120.00	601
Remove & refix o/s cushion seat	\$	400.00	2
Remove & refix garnish, carpet	\$	400.00	} 801
Remove & refix upholstery	\$	450.00	
	\$	16,434.11	
Plus : 9% GST	\$	1,479.07	
Grand Total	\$	17,913.18	