

8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @KAKI BUKIT
SINGAPORE 415875

CLAIM DETAILS: PARTS

CLAIM DETAILS: PARTS		ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER	Distorted	1	\$ 1,218.30	\$ 1,218.30
2	REAR BUMPER SIDE HOLDER	cracked	1	\$ 58.20	\$ 58.20
3	REAR END PANEL	Rear	1	\$ 781.70	\$ 781.70
4	REAR END PANEL TOP GARNISH	new	1	\$ 374.10	\$ 374.10
5	TAILLAMP	sampled	1	\$ 548.40	\$ 548.40
6	TAILLAMP BRACKET	Distorted	1	\$ 50.50	\$ 50.50
7	TAILLAMP PANEL	Distorted	1	\$ 283.40	\$ 283.40
8	TAILGATE	Rear new	1	\$ 1,345.10	\$ 1,345.10
9	TAILGATE LOCK		1	\$ 374.90	\$ 374.90
10	TAILGATE WEATHERSTRIPE		1	\$ 355.10	\$ 355.10
11	TAILGATE INNER TRIM COVER		1	\$ 481.10	\$ 481.10
12	TAILGATE LOWER GLASS C/W MOULDING		1	\$ 988.40	\$ 988.40
13	TAILGATE GLASS MOULDING		1	\$ 182.90	\$ 182.90
14	TAILGATE OUTER GARNISH		1	\$ 722.10	\$ 722.10
15	TOYOTA LOGO		1	\$ 68.50	\$ 68.50
16	PRIUS WORDING		1	\$ 58.10	\$ 58.10
17	HYBRID EMBLEM		1	\$ 65.60	\$ 65.60
18	REAR FENDER	Distorted	1	\$ 1,062.30	\$ 1,062.30
19	REAR FENDER INNER PANEL	Distorted	1	\$ 561.20	\$ 561.20
20	REAR FENDER INNER SHIELD	torn	1	\$ 180.20	\$ 180.20
21	REAR FENDER INNER TRIM COVER	Distorted	1	\$ 307.10	\$ 307.10
22	REAR FENDER AIR VENT	Distorted	1	\$ 71.50	\$ 71.50
23	REAR FENDER GLASS C/W MOULDING	new	1	\$ 485.40	\$ 485.40
24	SPARE TYRE PANEL	Distorted	1	\$ 1,105.80	\$ 1,105.80
25	SPARE TYRE PANEL TOP BOARD	Distorted	1	\$ 542.10	\$ 542.10
26	SPARE TYRE PANEL TOOLS TRAY SPONGE	new	1	\$ 541.40	\$ 541.40
27	SPARE TYRE PANEL LOCK SCREW	new	1	\$ 39.40	\$ 39.40
28	SPARE TYRE PANEL BASE SPONGE	new	1	\$ 124.70	\$ 124.70
29	SPARE TYRE PANEL UNDERCOVER	new	1	\$ 298.40	\$ 298.40
30	REAR AXLE	Best	1	\$ 1,850.60	\$ 1,850.60
31	REAR WHEEL HUB C/W BEARING	Distorted	1	\$ 540.60	\$ 540.60
32	REAR SHOCK ABSORBER	Best	1	\$ 310.20	\$ 310.20
33	REAR DOOR	Distorted	1	\$ 1,547.60	\$ 1,547.60
34	REAR DOOR LOCK	new	1	\$ 348.10	\$ 348.10
35	REAR DOOR WEATHERSTRIPE	new	1	\$ 290.60	\$ 290.60
36	REAR DOOR VERTICAL WEATHERSTRIPE	new	1	\$ 142.20	\$ 142.20

37	ROCKER PANEL OUTER SKIRTING <i>Defunct</i>	1	\$	789.90	\$ 789.90
38	FRONT DOOR <i>Distorted</i>	1	\$	1,644.50	\$ 1,644.50
39	FRONT DOOR LOCK <i>Tanned</i>	1	\$	366.60	\$ 366.60
40	FRONT DOOR WEATHERSTRIPE <i>tom</i>	1	\$	298.70	\$ 298.70
41	FRONT DOOR OUTER HANDLE <i>Distorted</i>	1	\$	187.90	\$ 187.90
42	FRONT DOOR OUTER HANDLE END PIECE <i>new</i>	1	\$	60.90	\$ 60.90
43	FRONT DOOR GLASS REGULATOR GEAR <i>Distorted</i>	1	\$	310.20	\$ 310.20
44	FRONT DOOR REGULATOR MOTOR <i>new</i>	1	\$	487.10	\$ 487.10
45	FRONT DOOR INNER TRIM BOARD <i>new</i>	1	\$	622.50	\$ 622.50
46	FRONT DOOR WING MIRROR <i>new</i>	1	\$	1,023.10	\$ 1,023.10
47	FRONT BUMPER <i>Distorted</i>	1	\$	1,230.40	\$ 1,230.40
48	FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$	45.60	\$ 45.60
49	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$	529.40	\$ 529.40
50	FRONT BUMPER SPONGE <i>new</i>	1	\$	172.50	\$ 172.50
51	FRONT BUMPER FOG LAMP <i>new</i>	1	\$	265.60	\$ 265.60
52	FRONT BUMPER SIGNAL LAMP <i>new</i>	1	\$	128.20	\$ 128.20
53	FRONT BUMPER LOGO <i>new</i>	1	\$	68.50	\$ 68.50
54	HEADLAMP <i>new</i>	1	\$	1,740.40	\$ 1,740.40
55	HEADLAMP NOZZLE PUMP <i>2 new</i>	1	\$	184.20	\$ 184.20
56	HEADLAMP NOZZLE PUMP COVER <i>new</i>	1	\$	52.20	\$ 52.20
57	FRONT FENDER <i>Distorted</i>	1	\$	738.10	\$ 738.10
58	FRONT FENDER INNER SHIELD <i>tom</i>	1	\$	180.10	\$ 180.10
59	FRONT FENDER GLASS MOULDING <i>new</i>	1	\$	35.30	\$ 35.30
60	FRONT FENDER EMBLEM <i>new</i>	1	\$	65.20	\$ 65.20
61	FRONT SHOCK ABSORBER <i>new</i>	1	\$	493.90	\$ 493.90
62	FRONT LOWER ARM <i>new</i>	1	\$	625.90	\$ 625.90
63	FRONT KNUCKLE ARM <i>new</i>	1	\$	585.60	\$ 585.60
64	FRONT WHEEL HUB C/W BEARING <i>new</i>	1	\$	485.90	\$ 485.90
65	FRONT ANTI ROLL BAR <i>new</i>	1	\$	348.80	\$ 348.80
66	FRONT ANTI ROLL BAR LINKAGE <i>new</i>	1	\$	120.60	\$ 120.60
67	FRONT DRIVE SHAFT <i>new</i>	1	\$	1,764.40	\$ 1,764.40
68	STEERING CROSSMEMBER <i>new</i>	1	\$	1,952.50	\$ 1,952.50
69	STEERING RACK & PINION <i>new</i>	1	\$	2,603.40	\$ 2,603.40

22516.50

16887.37

TOTAL PRICE: \$ 38,514.20
 LESS 25% \$ 9,628.55
 SUB TOTAL PRICE: \$ 28,885.65

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00
3	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
5	TAILGATE INNER TRIM COVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
6	TAILGATE LOWER GLASS SEALANT <i>new</i>	1 SET	\$ 50.00	\$ 50.00
7	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
8	REAR FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
9	REAR FENDER INNER TRIM COVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
10	REAR FENDER GLASS SEALANT <i>new</i>	1	\$ 50.00	\$ 50.00
11	SPARE TYRE PANEL UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
12	REAR TYRE <i>new</i>	1	\$ 280.00	\$ 280.00

13	REAR WHEEL RIM <i>cut</i>	1	\$	680.00	\$ 680.00 <i>4w</i>
14	REAR DOOR BLACK TAPE <i>new</i>	1	\$	60.00	\$ 60.00 <i>✓</i>
15	REAR DOOR VISOR <i>new</i>	1	\$	60.00	\$ 60.00 <i>✓</i>
16	ROCKER PANEL OUTER SKIRTING CLIPS <i>new</i>	1 SET	\$	30.00	\$ 30.00 <i>✓</i>
17	FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$	30.00	\$ 30.00 <i>✓</i>
18	FRONT DOOR BLACK TAPE <i>new</i>	1	\$	60.00	\$ 60.00 <i>✓</i>
19	FRONT DOOR VISOR <i>new</i>	1	\$	60.00	\$ 60.00 <i>✓</i>
20	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$	30.00	\$ 30.00 <i>✓</i>
21	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$	30.00	\$ 30.00 <i>✓</i>
22	FRONT FENDER GLASS SEALANT <i>new</i>	1	\$	50.00	\$ 50.00 <i>30</i>
23	FRONT TYRE <i>new</i>	1	\$	280.00	\$ 280.00 <i>✓</i>
24	FRONT WHEEL RIM <i>cut</i>	1	\$	680.00	\$ 680.00 <i>4w</i>
			TOTAL :		\$ 3,000.00

1310

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 3,000.00	18w	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,600.00	18w	
3	WIRING CHECK	\$ 100.00	60	
4	TO APPLY TUFF COAT	\$ 250.00	120	
5	TO REMOVE UPHOLSTERY & REAR SEAT	\$ 300.00	80	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
7	TO REMOVE TAILGATE GLASS	\$ 180.00	X	
8	TO REMOVE TAILGATE LOWER GLASS	\$ 150.00	X	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	X	
10	TO TRANSFER REAR FENDER GLASS	\$ 100.00	60	
11	TO TRANSFER FRONT & REAR DOOR FITTINGS	\$ 300.00	120	
12	TO REMOVE HYBRID BATTERY	\$ 300.00	X	
13	TO PERFORM REPROGRAMMING OF HYBRID BATTERY	\$ 380.00	X	
14	TO REMOVE REAR UNDER CARRIAGE	\$ 380.00	280	
15	TO REMOVE FRONT UNDERCARRIAGE	\$ 350.00	200	
16	TO REMOVE STEERING CROSSMEMBER & STEERING RACK	\$ 350.00	250	
17	TO REMOVE FRONT FENDER GLASS	\$ 100.00	40	
18	TOWING FEES (KING ROLLER)	\$ 150.00	✓	

TOTAL: \$ 9,240.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 31,885.65

TOTAL LABOUR COST: \$ 9,240.00

TOTAL REPAIR COST: \$ 41,125.65

5010

total: 23207.37

4/s: 18.5k

18 Days

18.5k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: