

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNE 9881Y

REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	FRONT BUMPER	TORN	\$1,800.00	\$927.50	
1	FRONT BUMPER LOWER GRILLE	GRAZED	\$410.00	\$410.00	
1	FRONT FENDER N/S	DENTED/BENT	\$830.00	\$580.00	
1	FRONT WHEEL ARCH N/S	GRAZED	\$220.00	\$220.00	
1	HEADLIGHT N/S	CRACKED	\$2,250.00	\$2,150.30	
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	\$1,980.00	\$0.00	
	LESS 20.00% DISCOUNT		(\$1,498.00)	(\$857.56)	
			\$5,992.00	\$3,430.24	
Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	SET CLIPS, RIVETS & SCREWS (SN)	NECESSARY	\$100.00	\$30.00	
			\$100.00	\$30.00	
Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$1,500.00	\$750.00	
	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE, AND ALIGN ALL AFFACTED PORTIONS. INCLUSIVE OF THE REPAIR OF FRONT DOOR N/S		\$1,500.00	\$400.00	
	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE }		\$250.00	\$20.00	
	PROGRAMMING (HEADLIGHT) }		\$200.00	\$0.00	
	ALIGNMENT		\$120.00	\$60.00	

GRAND TOTAL	\$9,662.00	\$4,690.24			
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,750.00			
Report Ref No: CS/FCI24070080/Unp3m4					

\$3,570.00

\$1,230.00

CKS

MARCUS CHUA KANG SENG Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.